



CYCLE & CARRIAGE FRANCE PTE. LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



Company Reg No. 200609327M  
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Mr Ong Swee Chin Sydney		Cust No/Name /Mr Ong Swee Chin Sydney	
5, Pasir Ris Heights		Reg No/Reg Date SLE1771H / 15/11/2017	
Singapore 519212		Date In/Mileage / 0	
Contact No Mobile: 96780392		Chassis No VF73ABHZTHJ684036	
		Engine No 10JBHD3081826	
		Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML	
		Colour/Trim WPP BLANC BANQUISE / IXF YATAGO GREY	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00077	Cash	15/10/2024/ 19:01	TLK	282 / Kevin Leong	10494

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR ON FRT BUMPER (REI Frt bump for attachment replacement)				1140 2280.00
REPLACE ON FRT BONNET & AFFECTED AREA				1100 1680.00
E PNT98000 PAINT WORK ON FRT BUMPER & BONNET				1520 3040.00
E PNT88000 REPLACE RR BUMPER, TAILGATE & AFFECTED AREA				1100 2200.00
REPAIR ON END PANEL X				100 150.00
E PNT98000 PAINT WORK ON RR BUMPER, TAILGATE & END PANEL				100 150.00
E PNT88000 REMOVE & INSTALL RR PARKING ASSIST FOR FACILITATE REPAIR				380 400.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS				80 100.00
M SUNDRY APPLY WINDSCREEN SEALANT				230 250.00
E PNT88000 TRANSFER TAILGATE ATTACHMENTS TO NEW PANEL				160 200.00
E PNT88000 REMOVE & INSTALL BOOT COMPARTMENT FOR FACILITATE REPAIR				60 150.00
M SUNDRY APPLY SEALANT ON AFFECTED AREA				X 160.00
M SUNDRY PERFORM RUST PREVENTION				100 150.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				380.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				60 80.00
M SUNDRY SUPPLY C & C EMBLEM				20 50.00
M SUNDRY SUNDRIES				
M FRONT BUMPER X	1.00	1739.00	0.00	1739.00 X

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
Mr Ong Swee Chin Sydney 5, Pasir Ris Heights Singapore 519212	Cust No/Name /Mr Ong Swee Chin Sydney Reg No/Reg Date SLE1771H / 15/11/2017 Date In/Mileage / 0 Chassis No VF73ABHZTHJ684036 Engine No 10JBHD3081826 Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML Colour/Trim WPP BLANC BANQUISE / IXF YATAGO GREY
Contact No Mobile: 96780392	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00077	Cash	15/10/2024/ 19:01	TLK	282 / Kevin Leong	10494

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M CHEVRON EMBLEM SUPERIEUR <i>not</i>	1.00	292.00	0.00	292.00 X
M ENGINE BONNET ASS <i>ff</i>	1.00	1636.00	0.00	1636.00 ✓
M REAR BUMPER <i>cr</i>	1.00	1634.00	0.00	1634.00 ✓
M BUMPER BRACKET <i>Bay</i>	1.00	691.00	0.00	691.00 ✓
M BUMPER SKIRT <i>not</i>	1.00	539.00	0.00	539.00 X
M BRACKET SET <i>not</i>	1.00	233.00	0.00	233.00 X
M BRACKET SET LAT <i>not</i>	1.00	233.00	0.00	233.00 X
M BUMPER BRACKET <i>not</i>	1.00	491.00	0.00	491.00 ✓
M ANGLEPLATE <i>not</i>	1.00	82.00	0.00	82.00 X
M STIFFENER RH <i>not</i>	1.00	220.00	0.00	220.00 X
M ECU <i>not</i>	1.00	589.00	0.00	589.00 X
M BUMPER BRACKET <i>not</i>	1.00	151.00	0.00	151.00 X
M LOW RR PAN FIX <i>not</i>	1.00	223.00	0.00	223.00 X
M SENSOR SUPPORT <i>not</i>	1.00	269.00	0.00	269.00 X
M TAILGATE <i>not</i>	1.00	4192.00	0.00	4192.00 ✓
M TLGT EXT PANEL <i>not</i>	1.00	786.00	0.00	786.00 ✓
M TLGATE MOULDING <i>not</i>	1.00	463.00	0.00	463.00 X
M TAILGATE GLASS <i>not</i>	1.00	398.00	0.00	398.00 X
M WEATHERSTRIP <i>not</i>	1.00	212.00	0.00	212.00 X
M LOWER TRIM <i>not</i>	1.00	713.00	0.00	713.00 X
M TAILGATE FIX <i>not</i>	1.00	472.00	0.00	472.00 X
M BADGE (C4) <i>not</i>	1.00	91.00	0.00	91.00 ✓
M BADGE (PICASSO) <i>not</i>	1.00	91.00	0.00	91.00 ✓
M BADGE (CITROEN) <i>not</i>	1.00	114.00	0.00	114.00 ✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

SURVEYOR NAME: *Rose - 4090068*  
 SURVEYOR SIGNATURE: *Rose*  
 DATE: *23/10/24*  
 REMARKS: *7 days*

*9859*  
*6270*  
*16229*

Confirm & accepted by

Authorized signatory and company stamp

Parts	16,554.00
Labour	10,700.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	550.00
<b>Total (w/o GST)</b>	<b>27,804.00</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.