

TP Chin

Xiao Chin 25 Jun 2024

SLC 4347 R TOYOTA VIOS

No	Qty	Parts Description	Estimated Parts Price
1	1	Front headlamp -RH <i>new</i>	\$ 2,100.21 <i>x</i>
2	1	Front bumper <i>Re-use</i>	\$ 600.50 <i>x</i>
3	1	Front bumper side retainer <i>new</i>	\$ 50.14 <i>x</i>
4	1	Front fender -RH <i>Dented</i>	\$ 388.75 <i>x</i>
5	1	Front fender inner shield	\$ 120.10 <i>x</i>
6	1	Front wheel hub with bearing <i>new</i>	\$ 355.90 <i>x</i>
7	1	Front shock absorber	\$ 500.14 <i>x</i>
8	1	Front knuckle arm	\$ 600.54 <i>x</i>
9	1	Front lower arm <i>new</i>	\$ 750.11 <i>x</i>
10	1	Stabilizer bar link	\$ 280.60 <i>x</i>
11	1	Front door -RH <i>new</i>	\$ 1,111.33 <i>x</i>
12	1	Front door rubber <i>new</i>	\$ 130.50 <i>x</i>
13	1	Front door side mirror <i>Cracked</i>	\$ 588.75 <i>x</i>
			\$ 7,577.57
			\$ 1,894.39
			\$ 5,683.18

less 25%

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	1	Front bumper clip (1 set) <i>new</i>	\$ 80.00 <i>x</i>
2	1	Front fender inner shield clip (1 set) <i>new</i>	\$ 60.00 <i>x</i>
3	1	Front tyre	\$ 450.00 <i>x</i>
4	1	Front wheel rim -RH <i>new</i>	\$ 1,000.00 <i>x</i>
5	1	Front door black tape (1 set)	\$ 120.00 <i>x</i>
			\$ 1,710.00
Total parts :			\$ 7,393.18

No	Description	Labour Charges
1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 120.00 x
3	To remove and refit front undercarriage.	\$ 250.00 x
4	To conduct wheel alignment.	\$ 150.00 x
5	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 180.00 x
6	To apply undercoating on repaired and replaced panel.	\$ 200.00 x 30
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00 200
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00 500

Total labour :

\$ 4,080.00

Total parts :


\$ 7,393.18

Total labour :

\$ 4,080.00

Total repair cost :

\$ 11,473.18



Admin L
 L/s 25/06/24
 03 days.
 Total: 1493.12
 L/s: 12K