



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mdm Queenie Wong Lai Kleun 56 Bukit Batok East Avenue 5 #06-02 Singapore 659804 Mobile: 96393284				
		Document No. 0					
		Document Date 16/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZRE171R	GEXGKZ S2	18/03/2016	SFA9771Y	0	33907	79/DS/SFA9771Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH104545582		1ZRX552398	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP INS:CHINA TAIPING TP VEH:GBC5844J DATE OF ACC:15/10/2024 NUMBER OF REPAIR DAYS: SURVEY BY:				50 100.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				max 100.00	
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				792 2376.00	
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				656 1068.00	
5	B	BP-LAB2 TO CHECK WIRING SYSTEM				134.64	
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR				198.00	
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
8	1	S52159-0Z904 COVER, RR BUMPER	1.00	855.40		855.40	
9	2	S52462-02241 PAD, RR BUMPER, RH	1.00	8.80		8.80	
10	3	S52462-02201 PAD, RR BUMPER, RH	2.00	21.20		42.40	
11	4	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00	
12	5	S52562-02250 RETAINER, RR BUMPER	1.00	92.10		92.10	
13	6	S52563-02250 RETAINER, RR BUMPER	1.00	92.10		92.10	
14	7	S52575-02140 RETAINER, RR BUMPER	1.00	168.10		168.10	
15	8	S52576-02140 RETAINER, RR BUMPER	1.00	168.10		168.10	
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary			Total	
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others			Less Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mdm Queenie Wong Lai Kieun 56 Bukit Batok East Avenue 5 #06-02 Singapore 659804 Mobile: 96393284			
			Document No. 0					
			Document Date 16/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2015	ZRE171R	GEXGKZ S2	18/03/2016	SFA9771Y	0	33907	79/DS/SFA9771Y	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053REH104545582		1ZRX552398	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
16	9	S52023-02190 REINFORCEMENT SUB-AS ? x 11			1.00	615.60		615.60
17	0	S52181-02190 ARM, RR BUMPER, OUTE ? x 11			1.00	94.10		94.10
18	1	S52182-02160 ARM, RR BUMPER, OUTE ? x 11			1.00	94.10		94.10
19	2	SPZ061-12028 76 GREY METALLIC 2 REVERSE SENSOR ? x 11			1.00	158.30		158.30
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: <i>Handwritten notes:</i> Ap 9/10/2018 3 days 23/10/24 Res 44 paint								
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						7,521.74		
		Please acknowledge receipt of vehicle				GST 9.00% 676.96		
				Parts 2,447.10				
				Labour 5,074.64				
				Sublet 0.00				
				Lubrication/Fluid 0.00		Less 0.00		
				Others 0.00		Amount Due 8,198.70		



Borneo Motors

Incorporated in Singapore

Co. Reg No. : 196700086Z
GST Reg No. : MR-5500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6831 1188



TOYOTA

FINALIZATION ESTIMATE

Account Details		Account No.	Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079809 Attn: Motor Claims Dept		S1000003 / ICC11	Mdm Queenie Wong Lai Kieun 56 Bukit Batok East Avenue 5 #06-02 Singapore 659804 Mobile: 96393284				
		Document No. 0					
		Document Date 25/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZRE171R	GEXGKZ S2	18/03/2016	SFA9771Y	0	33907	79/DS/SFA9771Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH104545582		1ZRX552398	60	Ong Wen Hong	23/10/2024 8.00		25/10/2024 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP INS:CHINA TAIPING TP VEH:GBC5844J DATE OF ACC:15/10/2024 NUMBER OF REPAIR DAYS:03 REPAIR DAYS SURVEY BY:RASUL LKK				50.00	
2	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				792.00	
3	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				656.00	
4	B	BP-LAB2 TO CHECK WIRING SYSTEM				134.64	
5	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR				198.00	
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
7	1	S52159-0Z904 COVER, RR BUMPER	1.00	855.40		855.40	
8	2	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00	
9	3	SPC507-47009 00 BACK SENSOR (PRIMER) <i>short / (suppl)</i>	1.00	167.50		167.50	
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary		Total 3,109.54		
		Please acknowledge receipt of vehicle	Parts 1,080.90		GST 9.00% 279.85		
			Labour 2,028.64				
			Sublet 0.00				
			Lubrication/Fluid 0.00		Less 0.00		
			Others 0.00		Amount Due 3,389.40		

Company Copy