

TWIN WHEELS AUTO TRADING ENTERPRISE

38 Woodlands Industrial Park E1 #03-14

Singapore 757700

TEL: 6457 0410 / 6765 2616

EMAIL: twinauto@singnet.com.sg

Date : 17/10/2024

ATTN: MOTOR CLAIM DEPARTMENT

INSURED: MT SINGAPORE CAR RENTAL PTE LTD

H/P: 6765 2616

Dear Sirs / Madam,

Accident Claim for Vehicle No. SDT 9338 P, Involving Vehicle No. XD 2810 K.

Accident on 11/10/2024 at 10:10am along PIE.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	REAR BUMPER / BR	1PC	\$ 828.80
2	REAR BUMPER RETAINER / BR	2PCS	\$ 180.40
3	REAR BUMPER REFECTOR X	2PCS	\$ 197.00
4	REAR BUMPER REINFORCEMENT / DR	1PC	\$ 598.20
5	REAR BUMPER BRACKET / BT	2PCS	\$ 200.40
6	REAR BUMPER CLIP / PC	1SET	\$ 320.00
7	REAR BOOT LID / DR	1PC	\$ 1,294.10
8	REAR BOOT LID HINGS / BT	2PCS	\$ 280.40
9	REAR BOOT SPRING X	1SET	\$ 480.00
10	REAR BOOT LID INSULATOR / CRV	1PC	\$ 380.00
11	REAR BOOT REFECTOR / BR	2PCS	\$ 300.00
12	REAR BOOT HANDLE CHROME / BR	1PC	\$ 340.00
13	REAR BOOT LID LOCK / BT	1PC	\$ 320.00
14	REAR BOOT LID LOCK CATCH X	1PC	\$ 55.00
15	REAR BOOT LID RUBBER / TN	1PC	\$ 295.40
16	REAR BOOT LID LOCK SENSOR / BR	1PC	\$ 200.90
17	REAR NUMBER PLATE LAMP / BR	2PCS	\$ 288.90
18	REAR WINDSCREEN / BR	1PC	\$ 2,160.00
19	REAR WINDSCREEN MOULDING / DR	1SET	\$ 151.60
20	REAR END PANEL / DR	1PC	\$ 480.90
21	REAR END PANEL GARNISH / CRV	1PC	\$ 220.10
22	REAR R/H MUDGUARD / DR	1PC	\$ 1,770.00
23	REAR R/H MUDGUARD TRIM / CRV	1PC	\$ 450.20
24	REAR R/H MUDGUARD WHEELS HOUSING (inner) / DR	1PC	\$ 420.00
25	REAR R/H MUDGUARD MUDFLAT X	1PC	\$ 30.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)
17/10/24, 11.41am
m l
L/S

my lly
14 days

26	REAR R/H MUDGUARD COWLING X	1PC	\$	98.00
27	REAR L/H MUDGUARD / ON	1PC	\$	1,770.00
28	REAR L/H MUDGUARD COWLING X / TN	1PC	\$	98.00
29	REAR L/H MUDGUARD MUDFLAT X	1PC	\$	30.00
30	REAR L/H MUDGUARD INNER TRIM / TN	1PC	\$	450.20
31	REAR R/H DOOR X R	1PC	\$	1,900.00
32	REAR R/H DOOR LOCK ?	1PC	\$	780.00
33	REAR R/H DOOR RUBBER X	1PC	\$	200.00
34	REAR LAMP / BR	2PCS	\$	1,036.20
35	REAR LAMP PANEL / BT	1PC	\$	155.00
36	REAR LAMP RETAINER / BR	2PCS	\$	120.00
37	REAR SPEAKER PANEL / ON	1PC	\$	1,482.00
38	REAR SPEAKER PANEL COVER / TN	1PC	\$	855.70
39	REAR SPARE TYRE COVER / TN	1PC	\$	380.80
40	REAR SPARE TYRE PANEL X	1PC	\$	600.40
41	LOCK CABLE / TN	1PC	\$	120.00
42	REAR R/H TOP GARNISH / TN	1PC	\$	180.00
	TOTAL LIST PRICE		\$	22,498.60
	LESS 10%		-	2,249.86
	TOTAL AMOUNT		\$	20,248.74

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	REAR BOOT LID LOGO (COROLLA) / MR	1PC	\$ 80.10
2	REAR BOOT LID LOGO (ALTIS) / MR	1PC	\$ 98.40
3	REAR NUMBER PLATE / BR	1PC	\$ 40 50.00
4	REAR WINDSCREEN SEALANT / MR	1SET	\$ 40 80.00
5	REAR WINDSCREEN STICKER (PRIVATE HIRER) / MR	1PC	\$ 25.00
6	REAR REVERSE SENSOR / BR	1SET	\$ 280.00
7	REAR BOOT LID EMBLEM / MR	1PC	\$ 120.40
8	REAR REVERSE CAMERA X Stated	1SET	\$ 500.00
9	REAR BOOT LID CAMERA / Stated	1SET	\$ 280.00
	TOTAL SPECIAL NETT		\$ 1,513.90
	TOTAL AMOUNT		\$ 21,762.64

	LABOUR :	
1	LABOUR TO SPRAY PAINT	\$ 1700 1,800.00
2	LABOUR TO PANEL BEATING	\$ 1700 1,800.00
3	TO DISMANTLE WINDSCREEN	\$ 120 160.00
4	TO DISMANTLE CUSHION AND DRY UP CARPET	\$ 100 400.00
	TOTAL LABOUR	\$ 4,160.00
	TOTAL AMOUNT	\$ 25,922.64

FROM:

Twin Wheels Auto Trading Enterprise