

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURAI	NCE PTE LTD	Ref:	CS/LIP24100299/Anh3e2(N)	
	ONE RAFFLES QU NORTH TOWER S	JAY #25-01 IINGAPORE 048583	Date:	28/07/2025	
	ATTN: ANDY SEA	Н	Code	: LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 8737U	Veh. Inspected	YQ 6691E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	IVS24/1739	Excess (\$)	0.00	
	Assign From	ANDY SEAH	Assign Date	16/10/2024	
2.	. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2755	
	Engine No.	HIDDEN	Year of Reg.	2022	
	Chassis No.	JHHAGV4650K001500	Colour	WHITE	
	Odometer	229823 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
	L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
	R/H Rear Tyre	195 R15C	ARIVO	6 mm	
	L/H Rear Tyre	195 R15C	ARIVO	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	05/09/2024	Inspection Date	15/10/2024	
	Survey held at	TSL AUTO PRO SELECTION PTE LTD			
		BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
	A)REGISTRATION DATE: 26 APR 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	<u> </u>				