NOT Northarm 1/Ly & 6300/2 Purny After Pary 5day

## Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number: GBJ 7608A

S/N Parts Description  1 Rear tailgate RH ✓  2 Rear tailgate LH × repair  3 Rear tailgate logo ✓  4 Rear tailgate Citroen emblem ✓  5 Rear tailgate Berlingo emblem ✓  6 Rear tailgate lock X2  7 Rear tailgate windscreen LH ✓  8 Rear wiper arm  9 Rear wiper blade  10 Rear wiper arm cover ✓  11 Rear tailgate rubber X2 × not nec  12 Rear bumper ✓  13 Rear bumper retainer X2  15 Rear bumper reverse sensor ✓  16 Rear taillamp X2 ?	Unit Price Amt  \$1,620.00 \$1,620  \$1,550.00 \$1,550.00  \$1,550.00 \$1,550.00  \$1,550.00 \$1,90.00  \$1,09.00 \$109.00  \$1,28.00 \$128.00  \$1,28.00 \$128.00  \$1,6200 \$720.00  \$1,6200 \$720.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$108.00  \$1,6200 \$109.00  \$1,6200 \$
16 Rear taillamp X2 ? 17 Rear end panel 18 Rear No.plate lamp X2	7 \$899.00 \$899.00 X 10 \$126.00 \$252.00 X \$10,337
Special Nett  1 Rear No.plate ✓ 2 Rear windscreen sealant X2 ✓	101 \$50.00 \$50.00 \$510 102 \$60.00 \$120.00 \$400 \$110.00 \$170.00

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
   To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1

## Labour

1 To remove and refit affected parts, cut and weld affected arears.	\$900 <i>5001</i> V
2 To spray paint on affected areas. no need to spray paint rear bumpe	er \$900 <i>bad</i> 400
3 To remove and refit rear windscreen ✓ 40 (LH)	\$200 801
4 To transfer rear tailgate mechanism 60 (LH)	\$200 129
5 To remove and refit reverse sensor ✓	\$100 501
6 Tuff coat ✓	\$120 601
	\$2,420

Page 2