

ASS. REC. BY:

REF:

LIP / CS/LIP24100300/Kvh3

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

19/11/24

LS \$5500 confirmed with Jenny (red 7427, 57%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$


Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



Veh No: GBJ 7608A Yr Regn: 08, 19  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or A)  
 Make: Citroen Berlingo c.c. 1499  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 105801 T/Radio: Insured / Std / NI / NA  
 Eng/No:  
 C/No: VR 7 E F Y H Z R K J 55 4180  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modl: NII / S/Rlm / STD A/Rlm or  
 Tyre Size: F: 205 / 35 R 16  
 R:  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: 9 mm R/Bal. 9 mm  
 L/Bal. 9 mm R/Bal. 9 mm  
 D.O.A. 11/10/24 D.O.I. 24/10/2024  
 Survey held at  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Not Withstand  
 11/2yr & 6300h  
 Primary After Paint  
 5days

## Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : GBJ 7608A

### S/N Parts Description

- 1 Rear tailgate RH
- 2 Rear tailgate LH
- 3 Rear tailgate logo
- 4 Rear tailgate Citroen emblem
- 5 Rear tailgate Berlingo emblem
- 6 Rear tailgate lock X2
- 7 Rear tailgate windscreen LH
- 8 Rear wiper arm
- 9 Rear wiper blade
- 10 Rear wiper arm cover
- 11 Rear tailgate rubber X2
- 12 Rear bumper
- 13 Rear bumper reinforcement
- 14 Rear bumper retainer X2
- 15 Rear bumper reverse sensor
- 16 Rear taillamp X2
- 17 Rear end panel
- 18 Rear No.plate lamp X2

Unit Price	Amt	
Ry \$1,620.00	\$1,620	—
Ry \$1,550.00	\$1,550.00	—
me \$98	\$98.00	—
me \$109.00	\$109.00	—
me \$128.00	\$128.00	—
R \$305.50	\$611.00	X
Shatter \$720.00	\$720.00	✓
h \$108.00	\$108.00	X
h \$38.00	\$38.00	X
CRA \$18.00	\$18.00	✓
103-201m NLS CR \$206.40	\$412.80	50622
CRA \$1,217.60	\$1,217.60	—
Ry \$785.00	\$785.00	—
h \$162.00	\$324.00	X
me \$350.00	\$350.00	2001m
NLS CR \$548.20	\$1,096.40	4
R \$899.00	\$899.00	X
h \$126.00	\$252.00	X
	\$10,337	

### Special Nett

- 1 Rear No.plate
- 2 Rear windscreen sealant X2

me \$50.00	\$50.00	451m
me \$60.00	\$120.00	405m
	\$110.00	\$170.00

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Labour

1 To remove and refit affected parts, cut and weld affected areas.	\$900	5001
2 To spray paint on affected areas.	\$900	6001
3 To remove and refit rear windscreen	\$200	801
4 To transfer rear tailgate mechanism	\$200	1201
5 To remove and refit reverse sensor	\$100	501
6 Tuff coat	<u>\$120</u>	601
	\$2,420	

12,957

Page 2