

ASS. REC. BY:

REF:

VIP /

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

THH

of _____

9/6M

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

45K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4-5 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBJ 7608A

Yr Regn: _____

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

A

Make: _____

Citroen

Berlingo

c.c

1499

Colour: _____

Black

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

105801

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

VR 7 E F Y H Z R K J 554180

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

205 / 35 R 16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

9

mm

L/Bal. _____

9

mm

L/Bal. _____

9

mm

D.O.A. _____

11 / 10 / 24

D.O.A. _____

24 / 10 / 2024

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/11 11:20 80300L Cabin

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. St

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Not Withheld
 11 Sep & 6300h
 Primary After Repair
 5 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : GBJ 7608A

S/N Parts Description

- 1 Rear tailgate RH
- 2 Rear tailgate LH
- 3 Rear tailgate logo
- 4 Rear tailgate Citroen emblem
- 5 Rear tailgate Berlingo emblem
- 6 Rear tailgate lock X2
- 7 Rear tailgate windscreen LH
- 8 Rear wiper arm
- 9 Rear wiper blade
- 10 Rear wiper arm cover
- 11 Rear tailgate rubber X2
- 12 Rear bumper
- 13 Rear bumper reinforcement
- 14 Rear bumper retainer X2
- 15 Rear bumper reverse sensor
- 16 Rear taillamp X2
- 17 Rear end panel
- 18 Rear No.plate lamp X2

Unit Price	Amt	
<i>Ry</i> \$1,620.00	\$1,620	—
<i>Ry</i> \$1,550.00	\$1,550.00	—
<i>me</i> \$98	\$98.00	—
<i>me</i> \$109.00	\$109.00	—
<i>me</i> \$128.00	\$128.00	—
<i>R</i> \$305.50	\$611.00	X
<i>Shatter</i> \$720.00	\$720.00	✓
<i>in</i> \$108.00	\$108.00	X
<i>in</i> \$38.00	\$38.00	X
<i>CRA</i> \$18.00	\$18.00	✓
<i>103-201m NLS CR</i> \$206.40	\$412.80	50622
<i>CM</i> \$1,217.60	\$1,217.60	—
<i>Ry</i> \$785.00	\$785.00	—
<i>in</i> \$162.00	\$324.00	X
<i>me</i> \$350.00	\$350.00	2001m
<i>NLS CR</i> \$548.20	\$1,096.40	4
<i>R</i> \$899.00	\$899.00	X
<i>in</i> \$126.00	\$252.00	X
	\$10,337	

Special Nett

- 1 Rear No.plate
- 2 Rear windscreen sealant X2

<i>me</i> \$50.00	\$50.00	451m
<i>me</i> \$60.00	\$120.00	401m
	\$110.00	\$170.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour

1 To remove and refit affected parts, cut and weld affected areas.	\$900	5001
2 To spray paint on affected areas.	\$900	6001
3 To remove and refit rear windscreen	\$200	801
4 To transfer rear tailgate mechanism	\$200	1201
5 To remove and refit reverse sensor	\$100	501
6 Tuff coat	<u>\$120</u>	601
	\$2,420	