NOT Nothashir 11 Ly & 6300/r Presony After Pains 5days

## Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number: GBJ 7608A

2 Rear windscreen sealant X2

S/N Parts Description	Unit Price	Amt
1 Rear tailgate RH	**************************************	\$1,620
2 Rear tailgate LH	\$1,550.00	\$1,550.00
3 Rear tailgate logo	Ma \$98	\$98.00 —
4 Rear tailgate Citroen emblem	Ne, \$109.00	\$109.00 —
5 Rear tailgate Berlingo emblem	Mz \$128.00	\$128.00
6 Rear tailgate lock X2	N C205 50	\$611.00 🔨
7 Rear tailgate windscreen LH	Shatter \$720.00	\$720.00
8 Rear wiper arm	₾ \$108.00	\$108.00 🗸
9 Rear wiper blade	/h \$38.00	\$38.00 \( \)
10 Rear wiper arm cover	CM \$18.00	\$18.00
11 Rear tailgate rubber X2	103-2012 NIS Coy \$206.40	\$412.80 50lav
12 Rear bumper	\$200.40 \$1,217.60	
13 Rear bumper reinforcement	8785.00	\$785.00
14 Rear bumper retainer X2		
15 Rear bumper reverse sensor	∫∽ \$162.00 7.4 \$350.00	\$324.00 \$
16 Rear taillamp X2	nd \$350.00	\$350.00 2001n
6	M/ San \$548.20	\$1,096.40
17 Rear end panel	\$899.00	\$899.00 🗶
18 Rear No.plate lamp X2	1 \$126.00	\$252.00
	10)	\$10,337
0 1111111	· ·	
Special Nett	p. /	48.
1 Rear No.plate	\$50.00	\$50.00

## LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
   To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1

\$60.00

\$110.00

\$120.00 405m

\$170.00

## Labour

1 To remove and refit affected parts, cut and weld affected arears.	\$900	3001
2 To spray paint on affected areas.	\$900	6001
3 To remove and refit rear windscreen	\$200	801
4 To transfer rear tailgate mechanism	\$200	1201
5 To remove and refit reverse sensor	\$100	501
6 Tuff coat	\$120	601
	\$2,420	

Page 2