

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT	<i>Hui Rong.</i>
DATE:	17-10-24	
CLAIM TYPE:	T/P CLAIM	
TO:	INCOME	
VEHICLE DETAILS		
VEHICLE NO:	SNN3651L	
MAKE & MODEL:	TOYOTA SIENTA	
CHASSIS NO:		
ACCIDENT DETAILS		
DATE:	15 October, 2024	
TIME:	1340HRS	
THIRD PARTY REQUESTOR:	JACK LI	

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>2 Dashed</i>	1	\$ 2,088.30	\$ 2,088.30
2	TAIL GATE HYBRID EMBLEM <i>new</i>	1	\$ 75.00	\$ 75.00
3	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 180.00	\$ 180.00
4	REAR BUMPER <i>Dashed</i>	1	\$ 680.00	\$ 680.00
5	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 62.00	\$ 62.00
6	REAR BUMPER CENTRE RETAINER <i>new</i>	1	\$ 70.00	\$ 70.00
7	REAR BUMPER REFLECTOR <i>cut</i>	1	\$ 95.00	\$ 95.00
8	REAR BUMPER OUTER PROTECTOR <i>Missing</i>	1	\$ 280.00	\$ 280.00
9	REAR BUMPER SENSOR <i>new</i>	1	\$ 245.00	\$ 245.00
10	REAR BUMPER SENSOR UNIT <i>cut + new</i>	1	\$ 1,855.30	\$ 1,855.30
11	TAILLAMP RH <i>cut</i>	1	\$ 620.00	\$ 620.00
12	REAR FENDER <i>Right</i>	1	\$ 920.00	\$ 920.00
13	REAR FENDER AIR VENT <i>new</i>	1	\$ 95.00	\$ 95.00
14	REAR FENDER MUDFLAG <i>new</i>	1	\$ 180.00	\$ 180.00
15	REAR FENDER INNER TRIM BOARD <i>new</i>	1	\$ 580.00	\$ 580.00
16	REAR FENDER OUTER GARNISH <i>Missing</i>	1	\$ 680.00	\$ 680.00
17	REAR END PANEL <i>Right</i>	1	\$ 780.00	\$ 780.00
18	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 250.00	\$ 250.00

TOTAL PRICE \$ 9,735.60
LESS 25% \$ 2,433.90
SUB TOTAL PRICE \$ 7,301.70

3928
2946

1458

✓
✓
✓
✓

+
✓

✓
✓

+
✓

✓
+
580

+
+

+
+

+
+

+
+

540

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00
3	TAILGATE INNER TRIM CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
4	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 22.00	\$ 22.00
5	REAR FENDER INNER TRIM CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
6	REAR FENDER OUTER GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL TOP GARNISH CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
8	REAR END PANEL INSULATION SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00

TOTAL \$ 392.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,400.00	\$ 1,400.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,400.00	\$ 1,400.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00
4	WIRING CHECK	1	\$ 80.00	\$ 80.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
8	TRANSFER TAILGATE MECHANISM	1	\$ 120.00	\$ 120.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	1	\$ 120.00	\$ 120.00

TOTAL \$ 3,800.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	7,693.70
TOTAL LABOUR COST	\$	3,800.00
TOTAL REPAIR COST	\$	11,493.70

APPROVED DETAILS:

SURVEYOR:
CONTACT NO.:
PART BY PART/LUMP SUM
NO. OF DAYS

LKK As to Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Li

2/5 17/10/24

05 Days

Total: 4688

4/8: 3750