

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMM 2629B

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER PANEL	CUT	\$964.30	\$964.30
1	INSERT PANEL	NOT NECESSARY	\$148.00	\$0.00
1	TOW COVER	NOT NECESSARY	\$63.00	\$0.00
1	COVER BUMPER LOWER	СИТ	\$312.00	\$312.00
1	REAR LEFT SIDE TAILLAMP	CRACKED	\$434.90	\$434.90
1	REAR LEFT SIDE FENDER	TO REPAIR SEE LABOUR	\$3,548.15	\$0.00
1	REAR LEFT DOOR - DENT	TO REPAIR SEE LABOUR	\$1,315.90	\$0.00
1	REAR WHEEL ARCH LEFT	сит	\$173.80	\$173.80
1	REAR BUMPER REFLECTOR LH	CRACKED	\$54.67	\$54.67
1	ROCKER PANEL LOWER SIDE SKIRT LH	TORN	\$620.00	\$620.00
	LESS 0.00 / 5.00% DISCOUNT		\$0.00	(\$127.98)
			\$7,634.72	\$2,431.69

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET RIVET AND SCREW (SN)	NECESSARY	\$150.00	\$30.00
			\$150.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING AND CONNECTOR		\$150.00	\$20.00
	TO REAR LEFT DOOR	NOT NECESSARY	\$370.00	\$0.00
	TO REPLACE REAR LEFT FENDER INCLUDE CUT AND WELD. INCLUSIVE OF THE REPAIR OF REAR LEFT SIDE FENDER AND REAR LEFT DOOR - DENT. }		\$1,600.00	\$680.00
	TO REPLACE REAR BUMPER AND ATTACHEMENT PARTS }		\$300.00	\$0.00
	TO LEFT REAR WHEEL ARCH }		\$230.00	\$0.00
	TO RESPRAY THREE PANEL INCLUDE PUTTY		\$900.00	\$600.00
		\$3,550.00	\$1,300.00	

GRAND TOTAL	\$11,334.72	\$3,761.69



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$3,000.00	
Report Ref No: CS/INC24100303/Uvh3e2				

TOTAL FOR SPARE PARTS: \$ 7,784.72 \$ 2,461.69
TOTAL FOR LABOUR: \$ 3,550.00 \$ 1,300.00
TOTAL REPAIR COST: \$ 11,334.72 \$ 3,761.69

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.