

Estimate Cost Of repair: SMM2629B

Vehicle Model: F48/X1

WBAJG120705N13071

Spare Part:

Rear Bumper Panel	CUT ✓	\$	964.30 ✓
Insert Panel	RM X	\$	148.00 X
Tow cover	RM X	\$	63.00 X
Cover bumper lower	CUT ✓	\$	312.00 ✓
1 set Rivet and screw:	1 set 30 S/W	\$	150.00 30 S/W
Rear left side taillight lens	tail lamp CR ✓	\$	434.90 ✓
Rear left side fender	RM X	\$	3,548.15 X
Rear Left door-dent	RM X	\$	1,315.90 X
Rear wheel arch left	CUT ✓	\$	173.80 ✓
rear bumper reflector	RM CR ✓ 654.67 ✓	\$	7,110.05
Sub Total (5%)		\$	
Labour		\$	150.00 20
To check electrical wiring and connector		\$	11 370.00 X
To rear left door		\$	300.00 3 680
To replace rear bumper and attachment parts		\$	1,600.00
To replace rear left fender include cut and weld		\$	230.00
To left rear wheel arch		\$	900.00 600
To respray three panel include putty		\$	

SUB TOTAL

\$ 3,550.00

GRAND TOTAL

\$ 10,660.05

Rocker panel lower side skirt RM \$ 620.00 TR ✓

not Applied
in
main

90096608

H by S

17/10/24

1/5 \$ 3000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2558.67
52
P- 2431.69
S.W- 30
L- 1300
3761.69
202
3000