

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 17 Oct 2024

Preliminary Advice

Vehicle No	: SLC3277R	Accident Date	: 12/10/2024
Make	: MERCEDES-BENZ E200 KOMPRESSOR	Policy No.	: MPC24A00127000
Assignment Date	: 16/10/2024	Excess	: S\$1,000.00
Date of Inspection	: 17/10/2024	Est. Duration of Repair	: 8
Inspection At	: CONVERGENCE AUTOMOTIVE PTE LTD (HQ) 39 WOODLANDS CLOSE, MEGA@WOODLANDS #01-24 SINGAPORE 737856		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,694.50
Revised Amount	:S\$	12,217.50
Check Items (Estimated)	:S\$	2,376.00
Total	:S\$	14,593.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	13,452.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,548.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.