



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLZ 2908P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILLAMP O/S	BROKEN	\$580.60	\$520.80
1	REAR BUMPER SIDE O/S	CUT/DEFORMED	\$450.30	\$288.50
1	REAR BUMPER	CUT/TORN	\$950.80	\$764.20
1	REAR BUMPER REFLECTOR O/S	SERVICEABLE	\$138.10	\$0.00
1	REAR BUMPER SIDE RETAINER O/S	NOT NECESSARY	\$50.40	\$0.00
1	REAR FENDER WHEEL ARCH GARNISHE O/S	TORN	\$318.50	\$318.50
	LESS 20.00% DISCOUNT		(\$497.74)	(\$378.40)
			\$1,990.96	\$1,513.60
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$52.00	\$30.00
			\$52.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING		\$80.00	\$20.00
	TO RESPRAY PAINTING ON THE AFFECTED AREAS		\$800.00	\$380.00
	PANEL BEATING		\$500.00	\$200.00
			\$1,380.00	\$600.00
GRAND TOTAL			\$3,422.96	\$2,143.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,700.00
Report Ref No: CS/INC24100306/Uvh3e2				

TOTAL FOR SPARE PARTS: \$ 2,042.96 \$ 1,543.60
TOTAL FOR LABOUR : \$ 1,380.00 \$ 600.00
TOTAL REPAIR COST: \$ 3,422.96 \$ 2,143.60

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.