

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email : shawn7530@hotmail.com

Not Authorized
see
motor
18/10/24

2/5 \$ 1700
2 days
take photo

17 OCTOBER 2024

Vehicle No: SLZ2908P

Model : HONDA VEZEL

QTY	DESCRIPTION	AMOUNT
1	Rear to illamp 0/5	520.80 520 \$580.60 ✓
1	Rear Bumper Side 0/5	288.50 cur/de \$450.30 ✓
1	Rear Bumper	764.20 cur/de \$950.80 ✓
1	Rear Bumper Reflectors (R) 0/5	800 \$138.10 ✓
1	Rear Bumper Side Retainers (R) 0/5	nn \$50.40 ✓
1	Rear Fender Wheel Arch Garnishes 0/5	70.00 \$318.50 ✓
		\$2488.70
Less 20%		\$497.74
		\$1990.96

Special Nett Items

1 self	Rear Bumper Clip	nn \$52.00 30 S/N
		\$52.00

Labour Charges

1	To Remove, Replaced Damaged Lamps and check up Rear Wiring	\$80.00 20
1	To Respray Painting on the affected areas	\$800.00 380
1	Panel Beating	\$500.00 200
		\$1380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Grand Total **\$3422.96**

p-1892
202
1513.60
30
600
2143.60
202
1714