

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035962
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page 1 of 2
Your ref. DHOM110162271803
Job No. 74772
Our ref. 23.10.17
Payment
Date 16/10/2024

Attn

Vehicle No SFF 6263R
Vehicle Model : Lexus ES250
Accident on ... 15/10/2024

Not known

Runny Bypain

Ex TRA

2 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front bumper	420.00		<i>Bu</i> 420.00 ✓
1.00	Pc	Front bumper upper rubber seal	45.00		<i>m</i> 45.00 ✓
1.00	Pc	Front number plate base	70.00		<i>cm</i> 70.00 ✓
1.00	Pc	Front radiator grille	450.00		<i>cm</i> 450.00 ✓
1.00	Pc	Front radiator grille surround chrome	175.00		<i>cm</i> 175.00 ✓
1.00	Pc	Front bumper sponge	60.00		<i>cm</i> 60.00 ✓
1.00	Pc	Front tow hook cover	40.00		<i>nd</i> 40.00 ✓
1.00	Pc	Front bumper lower centre grille	250.00		<i>nd</i> 250.00 ✓
1.00	Pc	Front bumper lower centre grille chrome moulding	250.00		<i>cm</i> 250.00 ✓

Total amount of parts supplied - \$1,760.00

1.00	10% of parts supplied	176.00	176.00
------	-----------------------	--------	--------

Special Nett Item:

1.00	Front number plate	40.00	<i>Bu</i> 40.00 ✓
------	--------------------	-------	-------------------

headlamp - cca
\$2100

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

司拥有最先进的 CAROLINER MARK IV 机械, 可提供多种款式的车身及给予快速与准确的测量方式和大铁修理。
还有先进的 SAICO Deluxe 喷漆烘炉。
r services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support y system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO ix oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

ESTIMATE

EST. No: EST0035962
 United Overseas Insurance Ltd
 146 Robinson Road
 #02-01 UOI Building
 Singapore 068909

Page: 2 of 2
 Your ref.: DHOM110162271803
 Job No.: 74772
 Our ref.: 23.10.17
 Payment:
 Date: 16/10/2024

Attn

Vehicle No: SFF 6263R
 Vehicle Model : Lexus ES250
 Accident on ...: 15/10/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Labour & Misc:					
1.00		To check/clear fault codes after repair	80.00		80.00 <i>601</i>
1.00		To dismantle+renew above parts	250.00		250.00 <i>2201</i>
1.00		To respray paint	250.00		250.00 <i>✓</i>

Sub-Total 2,556.00
 GST 9.00% 230.04
 Total **SS** 2,786.04

司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
 ，还有先进的 SAICO Deluxe 喷漆烘炉。
 services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support
 system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO
 oven heater for re-spraying all motor vehicles."