



## Final Report

Estimate No. : **b1 71503**  
Date Estimated : **15/10/2024**  
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

- ESTIMATE REPAIR FOR -  
**Chua Ai Swan**  
**3 Elliot Walk**

- ACCOUNT - **144674**  
**ECICS Limited**  
**10 Eunos Road 8**  
**Singapore Post Centre #09-04A**  
**Singapore 408600**

**Singapore 458658**

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
<b>SFT77C</b>	<b>WBA1J72070V486863</b>	<b>29/11/2016</b>	<b>M235i COUPE</b>	<b>121570</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel, front RH door and attachments, RH system latch, RH sill strip, RH holding strips set include making good the rear RH fender and carrying out other necessary repairs caused by the accident	3,400.00		3,400.00
To spray paint rear bumper, rear RH fender, front RH door and RH side sill	3,940.00		3,940.00
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
To remove old PDC assembly, replace damaged parts and reconnect to bumper include conducting checks for proper function	177.00		177.00
To replace wheel rim include balancing (x1)	94.00		94.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (x1)	531.00		531.00
To carry out body cavity preservation (x1) (Per panel)	118.00		118.00
Sundries	150.00		150.00

### Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W



## Final Report

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 7.5X18 M DOUBLE SPK 436	1,139.35	1.00	0.00	1,139.35
FRT RH DOOR	1,479.50	1.00	0.00	1,479.50
# SET MOUNTS PDC SENSOR REAR (M)	62.95	1.00	0.00	62.95
REAR BUMPER PANEL PRIMED (M)	1,109.90	1.00	0.00	1,109.90
# RH SYSTEM LATCH	316.15	1.00	0.00	316.15
FRT RH OUTSIDE DOOR CHANNEL SEALING	114.40	1.00	0.00	114.40
FRT RH DOOR JOINT SEAL	87.75	1.00	0.00	87.75
RH SILL STRIP PRIMED (M)	386.20	1.00	0.00	386.20
RH HOLDING STRIPS SET (M)	128.35	1.00	0.00	128.35
# (DG/SL) ADHESIVE SET K6	60.20	1.00	0.00	60.20

### # SUPPLEMENTARY ITEMS

Total Labour :	8,587.00
Total Parts :	4,884.75
Total Labour & Parts (before GST) :	13,471.75
Deduction for Excess :	
Total Repair Costs less Excess:	13,471.75
GST @9%:	1,212.46
Grand Total :	14,684.21

### Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W