

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401555R GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71503
Date Estimated : 15/10/2024
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chua Ai Swan
3 Elliot Walk

Singapore 458658

- ACCOUNT - 144674
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT77C	WBA1J72070V486863	29/11/2016	M235i COUPE	121570

DESCRIPTION

To replace rear bumper, front rh door, side sill rh, attachments and make good of rear rh fender.

VALUE

5,100.00

3400

To painting rear bumper, rear rh fender, door rh and side sill rh.

3,940.00

To check electrical wiring system and lighting at the rear section for proper function.

177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

177.00

To replace tyre and wheel rim including balancing. (1x).

94.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

531.00

To carry out body cavity preservation.
(Per panel).

118.00

Sundries.

150.00

Total Labour 1:

10,287.00

DESCRIPTION

QTY

PRIC

VALUE

ALLOY RIM 7.5X18 M DOUBLE SPK 436 cut ✓

1

1,139.35

1,139.35

FRT RH DOOR bt ✓

1

1,479.50

1,479.50

RH SIDE GUIDE FOR BUMPER ? x sue

1

164.40

164.40

REAR BUMPER PANEL PRIMED (M) at ✓

1

1,109.90

1,109.90

FRT RH OUTSIDE DOOR CHANNEL SEALING m ✓

1

114.40

114.40

FRT RH DOOR JOINT SEAL m ✓

1

87.75

87.75

RH SILL STRIP PRIMED (M) de ✓

1

386.20

386.20

RH HOLDING STRIPS SET (M) m ✓

1

128.35

128.35

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 71503
Date Estimated : 15/10/2024
Prepared By : Inthiran A/L Thurasamy

Page No. :

- ESTIMATE REPAIR FOR -

Chua Ai Swan
3 Elliot Walk

- ACCOUNT - 144674
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

Singapore 458658

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SFT77C	WBA1J72070V486863	29/11/2016	M235i COUPE	121570

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTS PDC SENSOR REAR (M) <i>nm</i>	62.95	1.00	0.00	62.95
# RH SYSTEM LATCH <i>cm</i>	316.15	1.00	0.00	316.15
# (DG/SL) ADHESIVE SET K6 <i>nm</i>	60.20	1.00	0.00	60.20

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	439.30
Total Labour & Parts (before GST) :	439.30

Performance Motors Limited.
Sime Derby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

sime
MOTORS