

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate No: \_\_\_\_\_

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: \_\_\_\_\_

at Work / Home / Other

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vehicle: \_\_\_\_\_

\_\_\_\_\_

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: PC448SC Yr Regn: 2016 / Jan.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Isuzu LT434P C.D. 7790

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 508197 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JALLT434PF 7000138

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NN / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: 295/80R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firemax

Front 06 mm Rear 06 mm

R/Bal. 06 mm L/Bal. 06 mm

D.O.A. 06/11/24

Survey held at YSK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP SMRT

MV

PV

Nett

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

COE Expiry: \_\_\_\_\_

\_\_\_\_\_

Estimate given during: Yes ( )

1st Survey: No ( )

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

\_\_\_\_\_

\_\_\_\_\_

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

\_\_\_\_\_

649E