

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

TO	: SMRT	DATE	6/11/2024
VEHICLE NO	: PC4485C (2016)		
VEHICLE MODEL	: ISUZU LT434P		Xiao Chun.
CHASSIS NO	: JALLT434PF7000138		

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Repair</i>	1	\$ 3,200.00	\$ 3,200.00
2	REAR BUMPER REFLECTIVE STICKER <i>new</i>	1 SET	\$ 200.00	\$ 200.00
3	TAILLAMP <i>lot</i>	1	\$ 750.00	\$ 750.00
4	REAR UPPER SIGNAL LAMP <i>cracked</i>	1 SET	\$ 1,500.00	\$ 1,500.00
5	REAR BODY PANEL <i>cracked</i>	1	\$ 3,500.00	\$ 3,500.00
6	REAR BODY PANEL GLASS MOULDING <i>3 new</i>	1	\$ 280.00	\$ 280.00
7	REAR BODY PANEL GLASS SEALANT	1	\$ 60.00	\$ 60.00

TOTAL : \$ 9,490.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 2,000.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	800	
3	WIRING CHECK	\$ 150.00	30	
4	TO APPLY TUFF COAT	\$ 250.00	100	
5	TO REMOVE REAR BODY PANEL GLASS	\$ 250.00	180	

TOTAL: \$ 4,250.00

ESTIMATE REPORT

TOTAL PARTS COST:	\$	9,490.00
TOTAL LABOUR COST:	\$	4,250.00
TOTAL REPAIR COST:	\$	13,740.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4650

h/s: 3.7K

04 Days