

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035960
Chang Yong Chin Lawrence

Page 1 of 2
Your ref. TP-SH 7318X MS FC
Job No. 74765
Our ref. 24.10.15
Payment
Date 16/10/2024

Attn

Vehicle No SJR 3677P
Vehicle Model : Toyota Altis
Accident on ... 11/10/2024

*NOT Withdraw
C1 Rep & 1200h
Repair After Paim
2. day*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
Supply of Parts:						
1.00	Pc	Rear end panel	1,134.50	25.00	R 850.88	X
1.00	Pc	Rear bumper inner retainer LH	86.20	25.00	SL 64.65	X
1.00	Pc	Rear bumper outer retainer LH (No.2)	58.40	25.00	SL 43.80	X
1.00	Pc	Rear bumper outer retainer LH	122.10	25.00	SL 91.58	X
1.00	Pc	Rear bumper outer retainer LH	122.10	25.00	CM 91.58	X
1.00	Pc	Rear bumper <i>585.90</i>	1,607.70	25.00	CM 1,205.78	✓
1.00	Pc	Rear bumper absorber	216.10	25.00	CM 162.08	✓
1.00	Pc	Rear bumper absorber bracket LH	140.60	25.00	R 105.45	X
1.00	Pc	Rear bumper absorber bracket RH	140.60	25.00	R 105.45	✓
4.00	Pcs	Rear bumper lower clips	4.50	25.00	RE 13.50	✓
2.00	Pcs	Rear bumper retainer clips	3.50	25.00	RE 5.25	✓
Labour & Misc:						
1.00		To cut+weld rear end panel including renew above parts	800.00		800.00	250/
1.00		To knock and repair rear boot	250.00		250.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

本公司拥有最先进的 CARLINER MARK IV 机械，可提供精确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CARLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0035960
Chang Yong Chin Lawrence

Page: 2 of 2
Your ref.: TP-SH 7318X MS FC
Job No.: 74765
Our ref.: 24.10.15
Payment:
Date: 16/10/2024

Attn

Vehicle No: SJR 3677P
Vehicle Model : Toyota Altis
Accident on ...: 11/10/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To remove+refit reverse sensor	80.00		80.00 50¢
1.00		To respray paint rear end panel, rear bumper, rear boot etc	950.00		950.00 400¢

Sub-Total 4,820.00
GST 9.00% 433.80
Total S\$ 5,253.80

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."