

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SNQ7069B

No.	Qty	List Items	
1	1	Front bumper	\$ CM 1,211.90 ✓
2	1	Front bumper RH chrome finish <i>Crnk</i>	\$ Cr 144.60 ✓
3	1	Front bumper RH fog lamp cover	\$ Sn 144.60 X
4	1	Front bumper RH side retainer	\$ D11 22.70 ✓
5	1	Front bumper inner foam	\$ Sn 77.10 X
6	1	Front bumper inner reinforcement	\$ Rn 579.60 ✓
7	1	RH headlamp	\$ Cr 3,369.80 ✓ 4057.60
8	1	Front grille	mg \$ CM 202.60 ✓
9	1	Front grille centre "MAZDA" logo	\$ Rn 55.50 ✓
10	1	Front grille lower chrome finish	\$ Cr 79.00 ✓
11	1	Front RH fender	\$ R 383.70 X
12	1	Front top panel	mg \$ Cr 420.50 X
			20% \$ 6,691.60
			Less 10% \$ 669.16
			Total : \$ 6,022.44

Special Nett Items

13	1 Btl Radiator coolant	\$ Rn 50.00 X
----	------------------------	---------------

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 800.00 30d
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 60d
3	To check wirings and lightings.	\$ 40.00 2d
4	To remove, refit air con condenser, air con pipings/hoses, including vacuum & refill of air con gas.	\$ Rn 150.00 X
5	To supply and apply anti rust treatment	\$ Rn 80.00 X
		Total : \$ 2,070.00

Total Parts and Labour : \$ 8,142.44

*Not Withheld
L1 Rep & 505dk
Resurvey After Paint
4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: