



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLN1131H

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#22-00
SINGAPORE 048580
63476100

Vehicle & Document Information
WIP No 21499
Reg No/Reg Date SLN1131H / 29/01/2024
Date In/Mileage 04/11/2024/ 10782
Chassis No W1K1183842N4315285
Engine No 28281480047516
Make/Model MB/CLA 180 COUPE
Colour/Trim 021 149 Polar White/ 041 111 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator				
WI000576	Credit	16/01/2025/ 10:54	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 7240010118 // 11-10-2024								
DRIVE IN/TP VEH NUMBER : 15-10-2024 // SMX8770C - III								
DATE IN/DATE SURVEY: 4-11-2024 // RASUL - LKK								
DIRECT SETTLEMENT BY: 22-10-2024 // DAPHNE - LKK								
A BPILAB								1440.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES							0.05	1600.00
RESPRAY REAR BUMPER & TRUNK LID								
A BPILAB							0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
A BPILAB								120.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT								
M BPNSUN								15.00
SUNDRIES								
X REAR BUMPER					1.00	1463.03	00.00	1463.03
X REAR BUMPER LOWER BLACK TRIM					1.00	517.32	00.00	517.32
X RH/REAR BUMPER LOWER TRIM STRIP					1.00	146.70	00.00	146.70
X CLA 180 MODEL PLATE					1.00	224.29	00.00	224.29
X RIVET					4.00	6.50	00.00	26.00

Confirmed & accepted by

9% GST on **Nett** 5,932.34
5932.34 533.91

Authorized signatory and company stamp

Total Payable 6,466.25

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLN1131H

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#22-00
SINGAPORE 048580
63476100

Vehicle & Document Information

WIP No **21499**
Reg No/Reg Date **SLN1131H / 29/01/2024**
Date In/Mileage **04/11/2024/ 10782**
Chassis No **W1K1183842N4315285**
Engine No **28281480047516**
Make/Model **MB/CLA 180 COUPE**
Colour/Trim **021 149 Polar White/ 041 111 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	16/01/2025/ 10:55		371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 7240010118 // 11-10-2024 DRIVE IN/TP VEH NUMBER : 15-10-2024 // SMX8770C - III DATE IN/DATE SURVEY: 4-11-2024 // RASUL - LKK DIRECT SETTLEMENT BY: 22-10-2024 // DAPHNE - LKK X RIVET	4.00	6.50	00.00	26.00

Confirmed & accepted by

9% GST on **Nett 26.00** **26.00** **2.34**

Authorized signatory and company stamp

Total Payable 28.34

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg