

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3159/10/24 Your Ref: Date: 17th October 2024

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00
Singapore 048580

Name Of Insured : Mdm Yeo Phek Suan @ Cheng Sook Chin
Date Of Accident : 17/10/24 (08:00hrs)
Policy Number : D19MPC0004933_05

Estimate cost of repair to TOYOTA HARRIER (A) 2.0 SUV - SJC 3516 A

1 pc front n/s door	1215.00	\$ 2,870.95
1 pc front n/s door lower chrome moulding	one	198.27
1 pc front n/s side mirror comp (with lighting)	Daye	2,348.95
1 pc front n/s door outer chrome handle	cu	590.45
1 pc front n/s door lock chrome knob	su	89.16 X
1 pc front n/s door glass outer moulding	11	198.27 X
1 pc front n/s door glass regulator	su	417.25 X
16 pcs front n/s door trim board clips	11	68.00 X
1 pc rear n/s door lower chrome moulding	11	177.45 X
		\$ 6,958.75
	Less 25%	\$ 1,739.69
		\$ 5,219.06

To remove & refix front n/s door glass, regulator, inner lock, channel, weatherstrips, trim board, checker, hinge, moulding & necessary parts.

150.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.

650.00 400

To wiring check up for affected wiring system.

50.00 20

To putty & respray painting on all affected accident parts.

800.00 400

\$ 6,869.06

=====

Dollars : Six Thousand Eight Hundred Sixty Nine And Cents Six Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

r- 6008-62
252
4506.46
880
5386.46
205
4309