

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3159/10/24 Your Ref: Date: 25th Oct 2024



The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00
Singapore 048580

Name Of Insured : Mdm Yeo Phek Suan @ Cheng Sook Chin
Date Of Accident : 17/10/24 (08:00hrs)
Policy Number : D19MPC0004933_05

Cost of repair to TOYOTA HARRIER (A) 2.0 SUV - SJC 3516 A

To supply front n/s door, lower chrome protector, n/s side mirror comp, door outer handle & necessary parts.

To remove & refix front n/s door trim board, glass, regulator, channel, weatherstrip, inner lock, checker, hinge & necessary parts, including wiring check up.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out door pillar & necessary parts, to weld, renew & align above parts.

To putty & respray painting on all affected accident parts.

Lump Sum Repair : \$ 4,300.00
Less Excess : \$ 750.00

Cost Balance : \$ 3,550.00
=====

Dollars : Three Thousand Five Hundred And Fifty Only.

HUP MOTOR TRADING & SERVICE


.....

Encl : Discharge Voucher