

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24100319/Avp3e2	
	(BUDGET DIRECT I	NSURANCE)	Date:	25/11/2024	
	190 CLEMENCEAU SINGAPORE SHOP	PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLG 6764K	Veh. Inspected	SLP 9758L	
	Policy No.	-	Coverage	0	
	Claim No.	C10032273/KC	Excess	\$0.00	
	Assign From	KENNETH LIM	Assign Date	17/10/2024	
2.	2. Vehicle Details				
	Make & Model	MAZDA 3	C.C	1496	
	Engine No.	P520456796	Year of Reg.	23/06/2017	
	Chassis No.	JM6BN22A8H0164909	Colour	BLUE	
	Odometer	64067 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM	•		
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/60 R16	HABILEAD	6	
	L/H Front Tyre	205/60 R16	HABILEAD	6	
	R/H Rear Tyre	205/60 R16	HABILEAD	6	
	L/H Rear Tyre	205/60 R16	HABILEAD	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	16/10/2024	Inspection Date	17/10/2024	
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
5b.		Estimate Day	/s of Repair		

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days