

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN ANTHONY
BLK 295C COMPASSVALE CRESCENT #11-241
SINGAPORE 543295

Contact : 97306494 , 94359412

TP Budget Direct.
Veron.

TAX INVOICE

Repair Code : CLM16449

Date in : 16/10/2024

Vehicle Num. : SLP9758L

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0164909/P520456796

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT AIR DUCT <i>new</i>	1	97.70	+ 97.70
FRONT BONNET <i>Bushed</i>	1	1120.00	✓ 1,120.00
FRONT BONNET HINGES L/R <i>Best</i>	2	45.00	✓ 90.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	25.00	+ 50.00
FRONT BONNET INNER TOP RUBBER SEAL <i>new</i>	1	66.00	+ 66.00
FRONT BONNET MECHANISM LOCK <i>Dented</i>	1	207.00	✓ 207.00
FRONT BONNET MECHANISM LOCK COVER <i>new</i>	1	42.00	+ 42.00
FRONT BRACE PANEL <i>Best</i>	1	45.00	✓ 45.00
FRONT BUMPER <i>torn</i>	1	866.00	✓ 866.00
FRONT BUMPER INNER FOGLAMP BRACKET L/R <i>new</i>	2	43.00	+ 86.00
FRONT BUMPER LOWER GRILLE SIDE COVER L/R <i>new</i>	2	36.00	+ 72.00
FRONT BUMPER NUMBER PLATE GARNISH <i>Bushed</i>	1	85.00	✓ 85.00
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	502.00	✓ 502.00
FRONT BUMPER REINFORCEMENT OUTER COVER <i>crushed</i>	1	265.00	✓ 265.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	19.70	+ 39.40
FRONT BUMPER SIGNAL LAMP GARNISH L/R <i>new</i>	2	53.00	+ 106.00
FRONT BUMPER SIGNAL LAMP L/R <i>new</i>	2	147.00	+ 294.00
FRONT BUMPER TOP BRACKET <i>crushed</i>	1	95.60	✓ 95.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN ANTHONY
 BLK 295C COMPASSVALE CRESCENT #11-241
 SINGAPORE 543295

Contact : 97306494 , 94359412

TAX INVOICE

Repair Code : CLM16449

Date in : 16/10/2024

Vehicle Num. : SLP9758L

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0164909/P520456796

FRONT BUMPER TOP COVER	<i>Del d</i>	1	355.00	✓	355.00
FRONT BUMPER TOP COVER RIVET	<i>n</i>	4	5.90	✓	23.60
FRONT BUMPER TOW HOOK COVER	<i>2nd new</i>	1	18.00	✗	18.00
FRONT BUMPER UNDER COVER	<i>2nd n</i>	1	95.00	✗	95.00
FRONT GRILLE	<i>could</i>	1	145.00	✓	145.00
FRONT GRILLE 'LOGO' EMBLEM	<i>n</i>	1	61.00	✓	61.00
FRONT GRILLE CHROME MOULDING L/R	<i>could</i>	2	191.00	✓	382.00
FRONT GRILLE INNER BRACKET L/R	<i>could</i>	2	70.00	✓	140.00
FRONT GRILLE SIDE COVER L/R	<i>n</i>	2	80.00	✗	160.00
FRONT HEADLAMP CLIPS L/R	<i>n</i>	2	10.50	✗	21.00
FRONT HEADLAMP L/R	<i>could</i>	2	1580.00	✓	3,160.00
FRONT SUPPORT PANEL	<i>could</i>	1	493.00	✓	493.00
FRONT SUPPORT TOP PANEL	<i>n</i>	1	147.00	✗	147.00
REAR BOOTLID	<i>Back d</i>	1	1006.00	✓	1,006.00
REAR BOOTLID 'LOGO' EMBLEM	<i>2</i>	1	74.40	✓	74.40
REAR BOOTLID 'MAZDA3' EMBLEM	<i>new</i>	1	93.40	✓	93.40
REAR BOOTLID 'SKYACTIV' EMBLEM		1	63.60	✓	63.60
REAR BOOTLID HINGES L/R	<i>n</i>	2	145.30	✗	290.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN ANTHONY
BLK 295C COMPASSVALE CRESCENT #11-241
SINGAPORE 543295

Contact : 97306494 , 94359412

TAX INVOICE

Repair Code : CLM16449

Date in : 16/10/2024

Vehicle Num. : SLP9758L

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0164909/P520456796

REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	<i>new</i>	2	12.90	+	25.80
REAR BOOTLID INNER TRIM	<i>new</i>	1	120.20	+	120.20
REAR BOOTLID LOCK STRIKER	<i>new</i>	1	45.00	+	45.00
REAR BOOTLID MECHANISM LOCK	<i>and</i>	1	153.30	✓	153.30
REAR BOOTLID WEATHER STRIP	<i>let</i>	1	198.00	✓	198.00
REAR BUMPER	<i>Detached</i>	1	1128.60	✓	1,128.60
REAR BUMPER CENTER BRACKET	<i>could</i>	1	15.10	✓	15.10
REAR BUMPER REFLECTOR L/R	<i>could</i>	2	51.00	✓	102.00
REAR BUMPER REINFORCEMENT	<i>Detached</i>	1	628.70	✓	628.70
REAR BUMPER REVERSE SENSOR	<i>2 pieces done d</i>	4	198.00	396	792.00
REAR BUMPER REVERSE SENSOR HOLDER	<i>new 2 pieces</i>	4	75.00	150	300.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS	<i>new</i>	1	298.00	+	298.00
REAR BUMPER RIVET	<i>new</i>	4	5.90	✓	23.60
REAR BUMPER SIDE BRACKET L/R	<i>new</i>	2	21.00	+	42.00
REAR BUMPER SIDE RETAINER L/R	<i>new</i>	2	36.10	+	72.20
REAR BUMPER TOW HOOK COVER	<i>Detached</i>	2	16.20	✓	32.40
REAR END PANEL	<i>Detached</i>	1	505.10	✓	505.10
REAR END PANEL INNER TOP GARNISH	<i>could</i>	1	85.10	✓	85.10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN ANTHONY
BLK 295C COMPASSVALE CRESCENT #11-241
SINGAPORE 543295

Contact : 97306494 , 94359412

TAX INVOICE

Repair Code : CLM16449

Date in : 16/10/2024

Vehicle Num. : SLP9758L

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0164909/P520456796

REAR TAILLAMP INNER PANEL L/R	new	2	396.00	X	792.00
REAR TAILLAMP L/R	changed	2	535.00	✓	1,070.00
Subtotal before discount					17,286.40
Percentage discount 20%					3,457.28
Sub-total 1					13,829.12
FRONT BUMPER CLIPS - SET	new	1	60.00	30	60.00
FRONT BUMPER NUMBER PLATE	changed	1	25.00	✓	25.00
FRONT BUMPER NUMBER PLATE HOLDER	changed	1	50.00	30	50.00
RADIATOR COOLANT	new	1	80.00	50	80.00
REAR BOOTLID INNER TRIM CLIPS - SET	new	1	50.00	X	50.00
REAR BOOTLID NUMBER PLATE	new	1	25.00	X	25.00
REAR BOOTLID NUMBER PLATE HOLDER	new	1	50.00	X	50.00
REAR BUMPER CLIPS - SET	new	1	50.00	30	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	new	1	30.00	10	30.00
REAR TAILLAMP CLIPS L/R - SET	new	2	30.00	X	60.00
Subtotal before discount					480.00
Percentage discount 0%					0.00
Sub-total 2					480.00
Parts-total					14,309.12

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN ANTHONY
BLK 295C COMPASSVALE CRESCENT #11-241
SINGAPORE 543295

Contact : 97306494 , 94359412

TAX INVOICE

Repair Code : CLM16449

Date in : 16/10/2024

Vehicle Num. : SLP9758L

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0164909/P520456796

LABOUR

To transfer rear bootlid mechanism lock outer handle reflector

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	5,230.00
Parts & Labour Total	19,539.12

60 80.00
120 150.00
30 80.00
400.00
80.00
60 140.00
600 1,100.00
500 1,000.00
1400 2,000.00
60 200.00

2910

*** This is a computer-generated document which requires no signature.***

page 5

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
H/S 18/10/24

12 Days -

total: 13664.92

H/S 10.9K

total: 14093.40

H/S 11.21K ✓