



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKP 1669A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BENT	\$961.50	\$802.50
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	\$1,061.60	\$0.00
1	FRONT BUMPER EXTENSION LH	SERVICEABLE	\$48.00	\$0.00
1	FRONT BUMPER BRACKET LH	SERVICEABLE	\$222.40	\$0.00
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	\$153.50	\$153.50
1	FRONT BUMPER ABSORBER	SERVICEABLE	\$125.30	\$0.00
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	\$183.30	\$0.00
10	FRONT BUMPER CLIP	NECESSARY	\$55.00	\$55.00
2	FRONT BUMPER SENSOR	SERVICEABLE	\$500.00	\$0.00
1	HEADLAMP LH	MTG CRACKED	\$10,082.80	\$7,847.70
1	FOG LAMP LH	SERVICEABLE	\$361.60	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$3,438.75)	(\$2,214.68)
			\$10,316.25	\$6,644.02

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$800.00	\$300.00
	TO CHECK & RECONNECT ALL NECESSARY WIRING		\$150.00	\$20.00
	TO REMOVE & REFIT ALL SENSOR		\$100.00	\$60.00
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)		\$250.00	\$0.00
	TO SPRAY PAINTING ON THE AFFECTED AREA		\$800.00	\$320.00
			\$2,100.00	\$700.00

<b>GRAND TOTAL</b>			<b>\$12,416.25</b>	<b>\$7,344.02</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$5,850.00</b>
Report Ref No: CS/SPF24100325/Kvp3m4				

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$5,850-\$6,150

**KSC**

KENNETH KONG SENG CHEONG



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.