

ASS. REC. BY:

REF:

AGW/ CS/SPF24100325/Kvp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/ QD RES/ EVA/ INV/ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: QX 1783P

Policy No.

Claims No. ACS/105/009/2024/056(LK)

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

2018.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKP1669A

Yr Regn:

02 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Ty Harrie

C.C

1987

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

52753

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JT EAC3BH50J000128

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

11/10/24

D.O.I.

23/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

1st N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/10 21 Lm @ 5850.00 (red 6566.25, 52%)
repair range \$5850.00-6150.00

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: 2

1)

Date/Time, File Return to?

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation:

S - RS - SI

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	830H
Vehicle Details	
Vehicle No.:	SKP1669A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Oct 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 SUV (AUTO) (2WD)
Primary Colour:	Black
Manufacturing Year:	2020
Engine No.:	M20A5514392
Chassis No.:	JTEAC3BH50J000128
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$35,925.00
Original Registration Date:	24 Feb 2021
First Registration Date:	24 Feb 2021
Transfer Count:	1
Actual ARF Paid:	\$42,295.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2031
PARF Rebate Amount:	\$31,721.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,002.00
COE Rebate Amount:	\$29,203.00
Total Rebate Amount:	\$60,924.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 18 Oct 2024

OK

KBS Motorsports Pte Ltd



YOUR REF.: QX1783P
OUR REF.: SKP1669A

TO: SINGAPORE POLICE FORCE
CC: Claims Services Department

DATE: 21/10/2024
FROM: Lee Shirley
FAX: 6452 5333
CONTACT: 8686 5188

FAX:

*Not withoin
Resurvey B4 pain
2 day
L1 by @ 5850h*

MAKE & MODEL: TOYOTA HARRIER 2.0
SUV (AUTO) (2WD)
CHASSIS NO.: JTEAC3BH50J000128
ENGINE NO.: M20A5514392
YEAR MADE: 2021
ACCIDENT DATE: 11 October 2024

ESTIMATE FOR VEHICLE NO.: SKP1669A

NO.	DESCRIPTION	QTY.	LIST PRICE
1	FRONT BUMPER <i>802.50</i>	1	\$ 961.50 <i>L</i>
2	FRONT BUMPER REINFORCEMENT	1	\$ 1,061.60 <i>X</i>
3	FRONT BUMPER EXTENSION LH	1	\$ 48.00 <i>X</i>
4	FRONT BUMPER BRACKET LH	1	\$ 222.40 <i>X</i>
5	FRONT BUMPER SIDE RETAINER LH	1	\$ 153.50 <i>X</i>
6	FRONT BUMPER ABSORBER	1	\$ 125.30 <i>X</i>
7	FRONT BUMPER LOWER ABSORBER	1	\$ 183.30 <i>X</i>
8	FRONT BUMPER CLIP	10	\$ 55.00 <i>✓</i>
9	FRONT BUMPER SENSOR	2	\$ 500.00 <i>X</i>
10	HEADLAMP LH <i>7847.70</i>	1	\$ 10,082.80 <i>✓</i>
11	FOG LAMP LH	1	\$ 361.60 <i>X</i>
TOTAL:			\$ 13,755.00
LESS 25%:			\$ (3,438.75)
PARTS TOTAL:			\$ 10,316.25

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGE PARTS	\$ 800.00 <i>200</i>
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$ 150.00 <i>20</i>
TO REMOVE & REFIT ALL SENSOR	\$ 100.00 <i>60</i>
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$ 250.00 <i>X</i>
TO SPRAY PAINTING ON THE AFFECTED AREA	\$ 800.00 <i>220</i>
TOTAL:	\$ 12,416.25 <i>320</i>
9% GST:	\$ 1,117.46
GRAND TOTAL:	\$ 13,533.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KBS Motorsports Pte Ltd
160 SIN MING DRIVE, #06-03
SIN MING AUTOCITY
t 6451 5333 f 6452 5333
COMPANY REG. NO.: 200504627K