

KBS Motorsports Pte Ltd



YOUR REF.: QX1783P
OUR REF.: SKP1669A

TO: SINGAPORE POLICE FORCE
CC: Claims Services Department

DATE: 21/10/2024
FROM: Lee Shirley
FAX: 6452 5333
CONTACT: 8686 5188

MAKE & MODEL: TOYOTA HARRIER 2.0
SUV (AUTO) (2WD)

CHASSIS NO.: JTEAC3BH50J000128

ENGINE NO.: M20A5514392

YEAR MADE: 2021

ACCIDENT DATE: 11 October 2024

FAX:

*Not within
Resurveying
2 days
L1 Rm @ 5850h*

ESTIMATE FOR VEHICLE NO.: SKP1669A

NO.	DESCRIPTION	QTY.	LIST PRICE
1	FRONT BUMPER <i>802.50</i>	1	\$ 961.50 ✓
2	FRONT BUMPER REINFORCEMENT	1	\$ 1,061.60 X
3	FRONT BUMPER EXTENSION LH	1	\$ 48.00 X
4	FRONT BUMPER BRACKET LH	1	\$ 222.40 X
5	FRONT BUMPER SIDE RETAINER LH	1	\$ 153.50 X
6	FRONT BUMPER ABSORBER	1	\$ 125.30 X
7	FRONT BUMPER LOWER ABSORBER	1	\$ 183.30 X
8	FRONT BUMPER CLIP	10	\$ 55.00 ✓
9	FRONT BUMPER SENSOR	2	\$ 500.00 X
10	HEADLAMP LH <i>7847.70</i>	1	\$ 10,082.80 ✓
11	FOG LAMP LH	1	\$ 361.60 X
TOTAL:			\$ 13,755.00
LESS 25%:			\$ (3,438.75)
PARTS TOTAL:			\$ 10,316.25

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGE PARTS	\$ 800.00 <i>200</i>
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$ 150.00 <i>20</i>
TO REMOVE & REFIT ALL SENSOR	\$ 100.00 <i>60</i>
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$ 250.00 X
TO SPRAY PAINTING ON THE AFFECTED AREA	\$ 800.00 <i>220</i>
TOTAL:	\$ 12,416.25
9% GST:	\$ 1,117.46
GRAND TOTAL:	\$ 13,533.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KBS Motorsports Pte Ltd
160 SIN MING DRIVE, #06-03
SIN MING AUTOCITY
t 6451 5333 f 6452 5333

COMPANY REG. NO.: 200504627K