



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD  (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSONSINGAPORE 079914 ATTN: HEW LEE FONG			Ref: CS/AWA24060222/Aqh3m4 (N)  Date: 20/01/2025   Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	YQ 5249G	<b>Veh. Inspected</b>	XE 3977B
	<b>Policy No.</b>	BVFCB0015152400	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	NSV2400140/HLF	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	HEW LEE FONG	<b>Assign Date</b>	24/06/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HINO FS1ETNA	<b>c.c</b>	12913
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
	<b>Chassis No.</b>	JHDFS1ETNXXX10011	<b>Colour</b>	RED
	<b>Odometer</b>	250882 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	295/80R22.5	BRIDGESTONE	6 mm
	<b>L/H Front Tyre</b>	295/80R22.5	BRIDGESTONE	6 mm
	<b>R/H Rear Tyre</b>	295/80R22.5	BRIDGESTONE	6 mm
	<b>L/H Rear Tyre</b>	295/80R22.5	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	07/06/2024	<b>Inspection Date</b>	02/10/2024
	<b>Survey held at</b>	YAP LEE MOTOR  BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	