

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN SONG CHENG
29 BEGONIA DRIVE
SINGAPORE 809887

Contact : 96898327

TP Budget Direct.
Veron

TAX INVOICE

Repair Code : CLM18423

Date in : 15/10/2024

Vehicle Num. : SDH2884M

Model : TOYOTA LEXUS NX200T LUXURY S/R

Chassis/Eng# : JTJBARBZ302054108/8ARW172195

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delnd</i>	1	984.30	✓ 984.30
REAR BUMPER ANTENNA SENSOR <i>new</i>	1	120.00	120.00
REAR BUMPER LOWER LID <i>Delnd</i>	1	657.20	<i>580</i> 657.20
REAR BUMPER REFLECTOR L/R <i>new</i>	2	91.80	+ 183.60
REAR BUMPER REINFORCEMENT <i>new</i>	1	1262.10	1,262.10
REAR BUMPER REVERSE SENSOR <i>1 piece damaged</i>	4	630.40	<i>630</i> 2,521.60 <i>340</i>
REAR BUMPER REVERSE SENSOR 'O' RING <i>1 piece new</i>	4	25.00	<i>25</i> 100.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	36.70	+ 146.80
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	139.70	<i>x</i> 279.40
Subtotal before discount			6,255.00
Percentage discount 10%			625.50
Sub-total 1 <i>50</i>			5,629.50
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	✓ 50.00
Subtotal before discount			50.00
Percentage discount 0%			0.00
Sub-total 2			50.00
Parts-total			5,679.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SONG CHENG
 29 BEGONIA DRIVE
 SINGAPORE 809887

Contact : 96898327

TAX INVOICE

Repair Code : CLM18423
 Date in : 15/10/2024
 Vehicle Num. : SDH2884M
 Model : TOYOTA LEXUS NX200T LUXURY S/R
 Chassis/Eng# : JTJBARBZ302054108/8ARW172195

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

450

50	80.00
200	500.00
20	500.00
X	60.00

Labour Total	1,140.00
Parts & Labour Total	6,819.50

*** This is a computer-generated document which requires no signature.***

page 2

Admin [Signature]
 L/S 21/10/24
 02 Days.

Total: 223637

L/S: 1.8K

1.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: