

LEANG AUTOMOTIVE
BLK 1 KAKI BIKIT AVE 6 #01-68
AUTOBAY S'PORE 417883 HP 90286516

LKK Auto Consultants hence notify
the Repairer of the following:
• To survey before/after spray painting
• To display damaged parts for survey
• Parts prices are subject to confirmation
• No illegal modification(s) is allowed
• Any item(s) must be re-inspected and
is subject to final approval from Insurance Co., party

Not Authorized
Mr
meand
18/10/24
d/c a 5200/
take photo after rep-
6 days

VEHICLE No: SJX 6302U

Acknowledged by Repairer
Signature:
Date:

| | | | | |
|------|--|---------------|------------|------------|
| 1PC | BOOTLID | Buc | \$1,066.10 | ✓ |
| 1PC | BOOTLID REAR LOGO | ner | \$68.50 | ✓ |
| 1PC | BOOTLID INNER LOCK | tw | \$409.10 | ✓ |
| 1PC | BOOTLID LOCK STRICKER | nn | \$66.80 | X |
| 1PC | BOOTLID WEATHERSTRIP | tw | \$382.30 | ✓ |
| 1PC | BOOTLID OUTER HANDLE | nn | \$228.90 | X |
| 1PC | REAR BUMPER | Dis | \$685.10 | ✓ |
| 1PC | REAR BUMPER REFLECTOR O/S | cr | \$148.20 | ✓ |
| 2PCS | REAR BUMPER SIDE RETAINERS @\$65.00 | M/Sun o/s buf | \$130.00 | 1PC |
| 1SET | REAR BUMPER CLIPS | ner | \$50.00 | ✓ |
| 1PC | REAR END PANEL | body | \$788.20 | ✓ |
| 1PC | REAR END PANEL TOP GARNISH | 245-10 tw | \$362.30 | ✓ |
| 1PC | TAILLAMP O/S | CNA | \$488.20 | ✓ |
| 1PC | TAILLAMP GASKET O/S | ner | \$10.80 | ✓ |
| 1PC | TAILLAMP HOUSING PANEL O/S | body | \$290.50 | ✓ |
| 1PC | REAR FLOOR PANEL | R | \$1,145.20 | X |
| 1PC | REAR FLOOR PANEL TOP BOARD | born | \$320.50 | ✓ |
| 2PCS | REAR FLOOR PANEL SIDE TOOL SPONGES @\$328.00 | M/Sun o/s tw | \$656.00 | 1PC |
| 1PC | REAR FLOOR PANEL TOOL SPONGE INNER | born | \$266.10 | ✓ |
| 1PC | REAR FENDER O/S | R | \$991.80 | X |
| 1PC | REAR FENDER INNER TRIM O/S | re/torn | \$331.20 | ✓ |
| 1PC | REAR WINDSCREEN MOULDING | nn | \$92.80 | X |
| 1PC | REAR EXHAUST | R | \$845.10 | X |
| | | | \$9,823.70 | |
| | | | LESS 25% | \$7,367.78 |

S.NETT

| | | | | |
|------|----------------------------|-------------|----------|-----|
| 1SET | REAR BUMPER REVERSE SENSOR | malfunction | \$280.00 | 200 |
| 1PC | REAR END PANEL SEALANT | ner | \$50.00 | ✓ |
| 1SET | REAR FLOOR PANEL INSULATOR | nn | \$250.00 | X |
| 1PC | REAR LICENCE PLATE | nn | \$50.00 | X |

| | | |
|---|-------------|------|
| TO CHECK WIRING | \$50.00 | 20 |
| TO DISMANTLE & REPLACED REVERSE SENSOR | \$80.00 | 30 |
| TO DISMANTLE & REFIX BOOTLID MECHANISM | \$100.00 | 50 |
| TO DISMANTLE & REFIX CUSHION UPHOLSTERY | \$120.00 | 80 |
| TO DISMANTLE & REFIX REAR EXHAUST | \$100.00 | X |
| TO SPRAY RUST PROOFING | \$100.00 | 60 |
| LABOUR FOR PANEL BEATING & REPLACED PARTS | \$1,600.00 | 900 |
| TO PUTTY & SPRAY PAINTING | \$1,800.00 | 1100 |
| TOTAL | \$11,947.78 | |

+ 942.90
25%
14457.08