



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2501564

INV Date 17/03/2025

Reference CD/LPC24100329/Ema3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 4257A
Insured Veh. YM 9302E
Claim No. 23/24/24/VC05/030049
Policy No. Z23VC05020697
Accident Date 17/10/2024
Inspection Date 21/10/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24100329/Ema3q2
300 BEACH ROAD	Date:	17/03/2025
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	YM 9302E	Veh. Inspected	SHA 4257A
Policy No.	Z23VC05020697	Coverage	0
Claim No.	23/24/24/VC05/030049	Excess	\$0.00
Assign From	-	Assign Date	18/10/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	C.C	1798
Engine No.	2ZRS066731	Year of Reg.	23/12/2016
Chassis No.	JTDKB3FU403539086	Colour	BLUE
Odometer	816179 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	WESTLAKE	5
L/H Front Tyre	195/65 R15	WESTLAKE	5
R/H Rear Tyre	195/65 R15	WESTLAKE	5
L/H Rear Tyre	195/65 R15	WESTLAKE	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/10/2024	Inspection Date	21/10/2024
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHA 4257A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	BROKEN	\$503.04	\$503.04
10	REAR BUMPER CLIPS	NECESSARY	\$22.00	\$22.00
1	REAR FENDER RH	DENTED	\$992.04	\$992.04
1	PANEL SUB ASSY RR DOOR RH	TO REPAIR SEE LABOUR	\$1,258.30	\$0.00
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	\$94.80	\$0.00
1	REAR FENDER SHIELD RH	NOT NECESSARY	\$134.20	\$0.00
1	REAR WHEEL RIM RH	NOT NECESSARY	\$1,555.00	\$0.00
	LESS 25.00% DISCOUNT		(\$1,139.85)	(\$379.27)
			\$3,419.53	\$1,137.81
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR DOOR COMFORT APPS LOGO RH (SN)	NECESSARY	\$80.00	\$80.00
1	REAR TYRE RH (SN)	NOT NECESSARY	\$216.00	\$0.00
			\$296.00	\$80.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF PANEL SUB ASSY RR DOOR RH.	NOT NECESSARY	\$1,600.00	\$1,140.00
	SPRAY PAINTING CHARGE		\$900.00	\$840.00
	TRANSFER OF DOOR PARTS		\$120.00	\$0.00
	REMOVE/REFIX UPHOLSTERY RR /CUSHION		\$120.00	\$50.00
	REMOVE/REFIX REVERSE SENSOR		\$60.00	\$20.00
			\$2,800.00	\$2,050.00
GRAND TOTAL			\$6,515.53	\$3,267.81
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,600.00
Report Ref No: CD/LPC24100329/Ema3q2				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A






PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A




PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A



PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A



PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A



PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A




PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A



PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A



PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A



PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 4257A

