



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2500098

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 07/01/2025
Reference CD/CTI24100330/Uua3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SGZ 6228B
Insured Veh. SLL 3000A
Claim No. SNM24D205875
Policy No. DMPCSNA00078782403
Accident Date 18/10/2024
Inspection Date 21/10/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD	Ref:	CD/CTI24100330/Uua3q2
3 ANSON ROAD #16-00	Date:	07/01/2025
SPRINGLEAF TOWER SINGAPORE 079909	Code:	CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SLL 3000A	Veh. Inspected	SGZ 6228B
Policy No.	DMPCSNA00078782403	Coverage	0
Claim No.	SNM24D205875	Excess	\$0.00
Assign From	CECILIA LEE	Assign Date	21/10/2024

2. Vehicle Details

Make & Model	HONDA HRV 1.5 DX CVT	C.C	1496
Engine No.	L15B5671739	Year of Reg.	14/05/2019
Chassis No.	JHMRU1810JX201738	Colour	BLACK
Odometer	44223 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	DUNLOP	6
L/H Front Tyre	215/60R16	DUNLOP	6
R/H Rear Tyre	215/60R16	DUNLOP	6
L/H Rear Tyre	215/60R16	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/10/2024	Inspection Date	21/10/2024
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGZ 6228B

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR O/S	BENT /WARPED	\$1,109.20	\$966.20
1	FRONT DOOR INNER RUBBER O/S	NOT NECESSARY	\$188.90	\$0.00
1	SET FRONT DOOR FRAME STICKER O/S	NECESSARY	\$60.00	\$60.00
1	FRONT DOOR INNER LOCK O/S	NOT NECESSARY	\$345.80	\$0.00
1	REAR DOOR O/S	BENT /WARPED	\$1,122.80	\$952.20
1	REAR DOOR LOWER STICKER O/S	NECESSARY	\$48.00	\$48.00
1	REAR DOOR INNER RUBBER O/S	NOT NECESSARY	\$188.50	\$0.00
1	REAR DOOR INNER LOCK O/S	SERVICEABLE	\$345.80	\$0.00
1	SET REAR DOOR FRAME BLACK STICKER O/S	NECESSARY	\$60.00	\$60.00
1	REAR DOOR HINGES O/S	NOT NECESSARY	\$90.00	\$0.00
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	\$998.10	\$0.00
1	REAR FENDER OUTER PROTECTOR O/S	CUT/TORN	\$388.10	\$310.20
1	REAR BUMPER	NOT NECESSARY	\$762.00	\$0.00
1	SET REAR BUMPER CLIPS	NOT NECESSARY	\$50.00	\$0.00
1	REAR SPORT RIM O/S	TO REPAIR SEE LABOUR	\$1,100.00	\$0.00
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$479.32)
			\$6,857.20	\$1,917.28

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING		\$50.00	\$20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR	NOT NECESSARY	\$60.00	\$0.00
	TO SPRAY RUST PROOFING		\$80.00	\$60.00
	TO CONDUCT WHEEL ALIGNMENT	NOT NECESSARY	\$120.00	\$0.00
	TO RESET & REPROGRAMME SYSTEM	NOT NECESSARY	\$120.00	\$0.00
	TO DISMANTLE & REFIX BOTH N/S DOOR COMPONENTS		\$180.00	\$100.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$800.00	\$400.00
	TO PUTTY & SPRAY PAINTING		\$1,100.00	\$780.00
			\$2,510.00	\$1,360.00
GRAND TOTAL			\$9,367.20	\$3,277.28



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$2,600.00
Report Ref No: CD/CTI24100330/Uua3q2			

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B




PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B




PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B




PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 9 of 22)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 11 of 22)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 12 of 22)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 13 of 22)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 15 of 22)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B






LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 18 of 22)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 22 of 22)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 6228B

