

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CD/CT/24100330/4493

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGZ 6228B

at Workshop m/s

H

of

Insured:

SLZ 3000A

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$70k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

482E

Date:

Person Contacted:

Vehicle: IN / OUT

LTA 28869

Date / Time

Action / Instruction

Dep 13k.

25/10/24

have video of holden
L/S 2600 in hand Alan.

Veh No:

SGZ 6228B

Yr Regn:

14/05/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV 1.5

c.c

1496

Colour

Black

A/C:

Insured / Std / NI / NA

Sp.Reading

44223

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMRU1810JX201738

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/10/24

D.O.I.

21/10/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Workshop (\$

Report Format :

Lump Sum / I.B.I. (\$

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

NOT Authorized
for
works
21/10/24
2/s @ 2600
eligible. After up-
3 days.

VEHICLE No: SGZ 6228B

1PC	FRONT DOOR O/S	out/uegal	866.20	\$1,109.20	✓
1PC	FRONT DOOR INNER RUBBER O/S	11		\$188.90	X
1SET	FRONT DOOR FRAME STICKER O/S	nei		\$60.00	✓
1PC	FRONT DOOR INNER LOCK O/S	11		\$345.80	X
1PC	REAR DOOR O/S	out/uegal	852.20	\$1,122.80	✓
1PC	REAR DOOR LOWER STICKER O/S	nei		\$48.00	✓
1PC	REAR DOOR INNER RUBBER O/S	11		\$188.50	X
1PC	REAR DOOR INNER LOCK O/S	8vc		\$345.80	X
1SET	REAR DOOR FRAME BLACK STICKER O/S	nei		\$60.00	✓
1PC	REAR DOOR HINGE O/S	11		\$90.00	X
1PC	REAR FENDER O/S	R		\$998.10	X
1PC	REAR FENDER OUTER PROTECTOR O/S	cut/turn	310.20	\$388.10	✓
1PC	REAR BUMPER	11		\$762.00	X
1SET	REAR BUMPER CLIPS	11		\$50.00	X
1PC	REAR SPORT RIM O/S	R		\$1,100.00	X
				\$6,857.20	

(202)

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	11	\$60.00 X
TO SPRAY RUST PROOFING		\$80.00 60
TO CONDUCT WHEEL ALIGNMENT	11	\$120.00 X
TO RESET & REPROGRAMME SYSTEM	11	\$120.00 X
TO DISMANTLE & REFIX BOTH N/S DOOR COMPONENTS		\$180.00 100
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$800.00 400
TO PUTTY & SPRAY PAINTING		\$1,100.00 780
TOTAL		\$9,367.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2396.6
202
7917.28
1360
3277.28
202
111