



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24100332/Eqh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	27/12/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNQ 9019H	Veh. Inspected	SNN 3185R
Policy No.	-	Coverage	0
Claim No.	IVS24/1929	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	18/10/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA CROSS	C.C	1987
Engine No.	M20A5982744	Year of Reg.	29/11/2023
Chassis No.	JTNABACB40J024275	Colour	WHITE
Odometer	55305 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/50Z R18	FIRENZA	5
L/H Front Tyre	225/50Z R18	FIRENZA	5
R/H Rear Tyre	225/50Z R18	FIRENZA	5
L/H Rear Tyre	225/50Z R18	FIRENZA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/10/2024	Inspection Date	21/10/2024
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days