

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorised
as
means

21/10/24

d/s R 3200

Take ph. Add up ~
3 days

VEHICLE No: SJK 8565H

1PC	FRONT BUMPER	cur/tun	1512.32	\$2,115.32	✓
1PC	FRONT BUMPER BEAM	su		\$945.10	X
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	cur/tun	166.00	\$324.00	✓
1PC	FRONT BUMPER FOG LAMP O/S	one	345.20	\$450.00	✓
1SET	FRONT BUMPER CLIPS & RIVET	ner		\$60.00	✓
1PC	FRONT BUMPER LOGO	11		\$85.00	X
1PC	FRONT BUMPER SPONGE	tun	205	\$162.00	✓
1PC	FRONT BUMPER INNER TOP RETAINER	11		\$322.00	X
1PC	FRONT HEADLAMP O/S	holder one	1566.32	\$3,500.00	✓
1PC	FRONT SUPPORT PANEL	R		\$1,045.11	X
1PC	FRONT LICENCE PLATE	11		\$50.00	X
1PC	FRONT GRILLE ASSY	11		\$1,012.00	X
1PC	FRONT GRILLE LOGO	11		\$420.00	X
1PC	BONNET	11	102	\$2,111.25	X
2PCS	BONNET HINGES @\$350.00	11		\$700.00	X
				\$13,301.78	

TO CHECK WIRING

TO SPRAY RUST PROOFING

TO REFILL AIR CON GAS

LABOUR FOR PANEL BEATING & REPLACED PARTS

TO PUTTY & SPRAY PAINTING

	\$50.00	20
11	\$80.00	X
11	\$120.00	X
	\$680.00	300
	\$800.00	300
TOTAL	\$15,031.78	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3811-84

102

3430.65

620

4050.65

203

3240.