

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not Authorized
meraj

21/10/24

2/5 \$3400

3 days

Whisper After repair

VEHICLE No: SJK 8565H

1PC	FRONT BUMPER	cur/ torn	1512.32	\$2,115.32	—
1PC	FRONT BUMPER BEAM	scr		\$945.10	X
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	cur/ torn	166.00	\$324.00	—
1PC	FRONT BUMPER FOG LAMP O/S	one	345.20	\$450.00	—
1SET	FRONT BUMPER CLIPS & RIVET	new		\$60.00	—
1PC	FRONT BUMPER LOGO	11		\$85.00	X
1PC	FRONT BUMPER SPONGE	torn		\$162.00	—
1PC	FRONT BUMPER INNER TOP RETAINER	11		\$322.00	X
1SET	FRONT BUMPER CHROME MOULDING	new/one		\$232.00	—
1PC	FRONT HEADLAMP O/S	holder one	1566.32	\$3,500.00	—
1PC	FRONT SUPPORT PANEL	11		\$1,045.11	X
1PC	FRONT LICENCE PLATE	11		\$50.00	X
1PC	FRONT GRILLE ASSY	11		\$1,012.00	X
1PC	FRONT GRILLE LOGO	11		\$420.00	X
1PC	BONNET	11		\$2,111.25	X
2PCS	BONNET HINGES @\$350.00	11		\$700.00	X
				\$13,533.78	

(102)

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	11	\$80.00 X
TO REFILL AIR CON GAS	11	\$120.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$680.00 300
TO PUTTY & SPRAY PAINTING		\$800.00 300
TOTAL	\$15,263.78	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-404384
102
3639.45
620
4259.45
203
3407