



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2502928

16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN:KAREN TAN

INV Date 14/05/2025  
Reference CD/FCI24100335/Rua3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SCF 588D  
Insured Veh. SHC 2105H  
Claim No. D24008975MFCT/CTPL/TPD 2  
Policy No. D-24101861MFCT  
Accident Date 09/10/2024  
Inspection Date 29/10/2024

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 450.00        |
| <b>Subtotal</b>                | <b>450.00</b> |
| <b>GST (9%)</b>                | <b>40.50</b>  |
| <b>Grand Total</b>             | <b>490.50</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                    |                                                                                                                                        |                                                                  |                                                                 |            |
|----------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|-----------------------------------------------------------------|------------|
| MS FIRST CAPITAL INSURANCE LTD<br>16 RAFFLES QUAY<br>#42-01 HONG LEONG BUILDINGSINGAPORE<br>048581<br>ATTN:KAREN TAN |                                                                                                                                        |                                                                  | Ref: CD/FCI24100335/Rua3q2(N)<br>Date: 14/05/2025<br>Code: FCI2 |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                    |                                                                                                                                        |                                                                  |                                                                 |            |
|                                                                                                                      | Insured Veh.                                                                                                                           | SHC 2105H                                                        | Veh. Inspected                                                  | SCF 588D   |
|                                                                                                                      | Policy No.                                                                                                                             | D-24101861MFCT                                                   | Coverage (\$)                                                   | 0.00       |
|                                                                                                                      | Claim No.                                                                                                                              | D24008975MFCT/CTPL/TPD 2                                         | Excess (\$)                                                     | 0.00       |
|                                                                                                                      | Assign From                                                                                                                            | KAREN TAN                                                        | Assign Date                                                     | 29/10/2024 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                        |                                                                                                                                        |                                                                  |                                                                 |            |
|                                                                                                                      | Make & Model                                                                                                                           | B.M.W. 740I AT M SPORT                                           | c.c                                                             | 2979       |
|                                                                                                                      | Engine No.                                                                                                                             | HIDDEN                                                           | Year of Reg.                                                    | 2014       |
|                                                                                                                      | Chassis No.                                                                                                                            | WBAYA62060C994746                                                | Colour                                                          | BLACK      |
|                                                                                                                      | Odometer                                                                                                                               | 124203 KM                                                        | Steering                                                        | IN ORDER   |
|                                                                                                                      | Brakes                                                                                                                                 | IN ORDER                                                         | Modification                                                    | SPORTS RIM |
|                                                                                                                      | General                                                                                                                                | FAIR                                                             |                                                                 |            |
| <b>3. Conditions of Tyres</b>                                                                                        |                                                                                                                                        |                                                                  |                                                                 |            |
|                                                                                                                      |                                                                                                                                        | Size                                                             | Make                                                            | Balance    |
|                                                                                                                      | R/H Front Tyre                                                                                                                         | 245/45 R19                                                       | PIRELLI                                                         | 6 mm       |
|                                                                                                                      | L/H Front Tyre                                                                                                                         | 245/45 R19                                                       | PIRELLI                                                         | 6 mm       |
|                                                                                                                      | R/H Rear Tyre                                                                                                                          | 245/45 R19                                                       | PIRELLI                                                         | 6 mm       |
|                                                                                                                      | L/H Rear Tyre                                                                                                                          | 245/45 R19                                                       | PIRELLI                                                         | 6 mm       |
| <b>4. Description of Damages</b>                                                                                     |                                                                                                                                        |                                                                  |                                                                 |            |
|                                                                                                                      | THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.<br>DAMAGES SEE DETAILS.                                                         |                                                                  |                                                                 |            |
| <b>5. General Information</b>                                                                                        |                                                                                                                                        |                                                                  |                                                                 |            |
|                                                                                                                      | Accident Date                                                                                                                          | 09/10/2024                                                       | Inspection Date                                                 | 29/10/2024 |
|                                                                                                                      | Survey held at                                                                                                                         | PERFORMANCE MOTORS LTD<br>303 ALEXANDRA ROAD<br>SINGAPORE 159941 |                                                                 |            |
| <b>5a. Remarks</b>                                                                                                   |                                                                                                                                        |                                                                  |                                                                 |            |
|                                                                                                                      | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                  |                                                                 |            |
| <b>5b. Estimate Days of Repair</b>                                                                                   |                                                                                                                                        |                                                                  |                                                                 |            |
|                                                                                                                      | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                  | 5 Working Days                                                  |            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCF 588D

| Qty | Description of Parts                                                                                                                            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                                                                                              |                      |                           |                   |
| 1   | SUNDRIES (SN)                                                                                                                                   | NECESSARY            | 150.00                    | 80.00             |
| 1   | ALLOY RIM 9.5JX19M V SPOKE 302 (SN)                                                                                                             | TO REPAIR SEE LABOUR | 1,657.20                  | -                 |
| 1   | RR BUMPER RH MOUNT (SN)                                                                                                                         | NOT NECESSARY        | 208.45                    | -                 |
| 1   | RR BUMPER (M-PDC) (SN)                                                                                                                          | SCRATCHED            | 2,315.60                  | 2,315.60          |
| 1   | REAR RH LIGHT IN SIDE PANEL (SN)                                                                                                                | SCRATCHED            | 881.80                    | 881.80            |
| 4   | DECOUPLING RING PDC TORQUE CONVERTE (SN)                                                                                                        | NECESSARY            | 23.00                     | 23.00             |
|     |                                                                                                                                                 |                      | 5,236.05                  | 3,300.40          |
|     | <b><u>LABOUR</u></b>                                                                                                                            |                      |                           |                   |
|     | TO REPLACE REAR BUMPER ,TAIL LAMP RH ,MAKE GOOD OF REAR RH FENDER AND REAR RH DOOR .INCLUSIVE OF THE REPAIR OF ALLOY RIM 9.5JX19M V SPOKE 302 . |                      | 3,400.00                  | 1,700.00          |
|     | TO PAINTING REAR BUMPER ,REAR RH FENDER AND REAR RH DOOR & REAR RH WHEEL RIM .                                                                  |                      | 3,256.00                  | 2,518.00          |
|     | TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.                                                         |                      | 177.00                    | 177.00            |
|     | TO REMOVE OLD PDC ASSEMBLY REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.                       |                      | 177.00                    | 177.00            |
|     | TO REPLACE WHEEL RIM INCLUDING BALANCING .                                                                                                      |                      | 94.00                     | 94.00             |
|     | TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS .                                                  |                      | 531.00                    | 531.00            |
|     |                                                                                                                                                 |                      | 7,635.00                  | 5,197.00          |
|     | <b>GRAND TOTAL</b>                                                                                                                              |                      | <b>12,871.05</b>          | <b>8,497.40</b>   |
|     | <b>RECOMMENDED COST OF REPAIRS</b>                                                                                                              |                      |                           | <b>8,497.40</b>   |

Report Ref No. CD/FCI24100335/Rua3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## PHOTOGRAPHS FOR VEHICLE NO. : SCF 588D



**PHOTOGRAPHS FOR VEHICLE NO. : SCF 588D**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 3 of 7)

### PHOTOGRAPHS FOR VEHICLE NO. : SCF 588D





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 4 of 7)

### PHOTOGRAPHS FOR VEHICLE NO. : SCF 588D



**PHOTOGRAPHS FOR VEHICLE NO. : SCF 588D**



**PHOTOGRAPHS FOR VEHICLE NO. : SCF 588D**



**PHOTOGRAPHS FOR VEHICLE NO. : SCF 588D**



**PHOTOGRAPHS FOR VEHICLE NO. : SCF 588D**

