



Final Report

Estimate No. : **b1 71501**
Date Estimated : 15/10/2024
Prepared By : Inthiran A/L Thurasamy

Page No. :

- ESTIMATE REPAIR FOR -

Chia Meng Chye
8 Galistan Avenue

Singapore 669680

- ACCOUNT -

303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SCF588D	WBAYA62060C994746	14/01/2014	740iA	68572

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel, rear RH light in side panel include making good the rear RH fender and carrying out other necessary repairs caused by the accident	1,700.00		1,700.00
** To spray paint rear bumper, rear RH fender and rear RH wheel rim	2,518.00		2,518.00
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
To remove old PDC assembly, replace damaged parts and reconnect to bumper include conducting checks for proper function	177.00		177.00
To replace wheel rim include balancing (x1)	94.00		94.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (x1)	531.00		531.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER (M-PDC)	2,315.60	1.00	0.00	2,315.60
REAR RH LIGHT IN SIDE PANEL	881.80	1.00	0.00	881.80
DECOUPLING RING PDC TORQUE CONVERTER	5.75	4.00	0.00	23.00

SUPPLEMENTARY ITEMS

Total Labour :	5,277.00
Total Parts :	3,220.40
Total Labour & Parts (before GST) :	8,497.40
Deduction for Excess :	
Total Repair Costs less Excess:	8,497.40
GST @9%:	764.77
Grand Total :	9,262.17

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

