

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SLV4851B

MAKE & MODEL: MAZDA 5

Not Authorized
Mr
Morgan
21/10/24
d/s #5500
Chap? Not. Allowed
S'days

| | | | |
|---------------------------------------|----------------|----------|----------------|
| TAILGATE | 201500 | 1637.00 | \$1,995.40 ✓ |
| TAILGATE LOGO | NU | | \$56.70 ✓ |
| TAILGATE SKYACTIV EMBLEM | NZ | | \$91.60 X |
| TAILGATE OUTER GARNISH | CNA | 266.50 | \$771.90 ✓ |
| TAILGATE LICENSE PLATE LAMP L/R X2 | 11 | | \$166.40 X |
| TAILGATE WINDSCREEN | 11 | | \$1,356.70 X |
| TAILGATE WINDSCREEN MOULDING SET | NU | | \$123.40 ✓ |
| TAILGATE WIPER ARM | 11 | | \$121.10 X |
| TAILGATE WIPER MOTOR | 11 | | \$515.30 X |
| TAILGATE LAMP L/R X2 | N/S one 0/5111 | 395.00 | \$1,346.80 1PC |
| TAILGATE LAMP GASKET L/R X2 | 11 | | \$238.80 X |
| TAILGATE INNER LOCK | Daye | 280.50 | \$384.60 ✓ |
| TAILGATE INNER TRIMBOARD | 11 | | \$516.90 X |
| TAILGATE WEATHERSTRIP | twi | 182.60 | \$251.40 ✓ |
| TAIL LAMP L/R X2 | N/S one 0/5111 | 651.20 | \$1,658.80 1PC |
| TAIL LAMP GASKET L/R X2 | 11 | | \$256.60 X |
| REAR BUMPER | 00102 | 1016.20 | \$1,411.30 ✓ |
| REAR BUMPER SIDE RETAINER L/R X2 | N/S Bent | 48.50 | \$168.80 1PC |
| REAR BUMPER BRACKET L/R X2 | 11 | | \$122.60 X |
| REAR BUMPER SIDE REFLECTOR L/R X2 | 11 | | \$162.40 X |
| REAR BUMPER REINFORCEMENT | 11 | | \$356.10 X |
| END PANEL | 00102 | 491.10 | \$885.70 ✓ |
| END PANEL GARNISH | twi | 181.20 | \$245.60 ✓ |
| FLOOR PANEL TOP BOARD | 11 | | \$585.30 X |
| FLOOR PANEL TOOL TRAY | twi/one | 401.20 | \$431.80 ✓ |
| FLOOR PANEL | R | | \$989.10 X |
| REAR FENDER LH | 11 | | \$1,532.20 X |
| REAR FENDER AIR VENT LH | 11 | | \$86.50 X |
| REAR FENDER INNER TRIMBOARD LH | 11 | | \$621.30 X |
| REAR FENDER GLASS LH C/W MOULDING | 11 | | \$489.70 X |
| REAR EXHAUST MUFFLER | R | | \$1,321.60 X |
| REAR EXHAUST MUFFLER RUBBER HANGER X2 | 11 | | \$78.60 X |
| | | | \$19,341.00 |
| | | Less 20% | \$3,868.20 |
| | | | \$15,472.80 |

1604

| | | | |
|------------------------------|--------------|----------|---------|
| REAR BUMPER CLIPS | NU | \$60.00 | 30 S/N |
| REAR BUMPER REVERSE SENSOR | Not in stock | \$280.00 | 200 S/N |
| REVERSE CAMERA | 11 | \$380.00 | X |
| TAILGATE OUTER GARNISH CLIPS | 11 | \$20.00 | X |
| TAILGATE WINDSCREEN SEALANT | NU | \$120.00 | 40 S/N |

| | | | |
|--------------------------------------|------|-------------------|--------|
| TAILGATE WINDSCREEN SPONGE | 111 | \$80.00 | 20 s/w |
| END PANEL GARNISH CLIPS | 11 | \$60.00 | X |
| END PANEL SEALANT | 111 | \$100.00 | 50 s/w |
| FLOOR PANEL SEALANT | 1 1 | \$100.00 | X |
| REAR FENDER INNER TRIMBOARD LH CLIPS | 1 1 | \$80.00 | X |
| REAR FENDER GLASS LH SEALANT | 1 1 | \$60.00 | X |
| REAR FENDER GLASS LH SPONGE | 1 1 | \$50.00 | X |
| REAR NUMBER PLATE WITH CASING | 5 12 | \$70.00 | 40 s/w |
| | | <u>\$1,460.00</u> | |

| | | | |
|--|-----|-------------------|-----|
| TO REPLACE REAR REVERSE SENSOR | | \$120.00 | 30 |
| TO REPLACE REAR REVERSE CAMERA | 1 1 | \$100.00 | X |
| TO CHECK REAR WIRING | | \$50.00 | 20 |
| TO REMOVE AND REFIT REAR WINDSCREEN | | \$150.00 | 120 |
| TO REMOVE AND REPLACE REAR FENDER LEFT QUARTER GLASS | 1 1 | \$120.00 | X |
| TO REMOVE AND REPLACE TAILGATE FITTINGS | | \$120.00 | 50 |
| TO REMOVE AND REPLACE REAR INTERIOR TRIMS & GARNISH | | \$200.00 | 60 |
| TO PROVIDE LABOUR, WORKMANSHIP | | \$1,800.00 | 600 |
| TO SPRAY PAINT ON AFFECTED PANELS | | \$1,400.00 | 900 |
| TO REMOVE AND REPLACE REAR EXHAUST MUFFLER | 1 1 | \$160.00 | X |
| RUST PROOFING | | \$200.00 | 50 |
| | | <u>\$4,420.00</u> | |

Total \$21,352.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

25835.1
202
4668.08
380
1830
6878.08
22
5202