

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SLV4851B

MAKE & MODEL: MAZDA 5

Not Authorized
Mr
morris
21/10/24
d/s # 5500
who? photo attached
S days

TAILGATE	10/5/20	1637.00	\$1,995.40	✓
TAILGATE LOGO	neu		\$56.70	✓
TAILGATE SKYACTIV EMBLEM	N7		\$91.60	X
TAILGATE OUTER GARNISH	CRQ	366.50	\$771.90	✓
TAILGATE LICENSE PLATE LAMP L/R X2	11		\$166.40	X
TAILGATE WINDSCREEN	11		\$1,356.70	X
TAILGATE WINDSCREEN MOULDING SET	neu		\$123.40	✓
TAILGATE WIPER ARM	11		\$121.10	X
TAILGATE WIPER MOTOR	11		\$515.30	X
TAILGATE LAMP L/R X2	N/S one 0/5/11	395.00	\$1,346.80	IPC
TAILGATE LAMP GASKET L/R X2	11		\$238.80	X
TAILGATE INNER LOCK	Daye	280.50	\$384.60	✓
TAILGATE INNER TRIMBOARD	11		\$516.90	X
TAILGATE WEATHERSTRIP	twi	182.60	\$251.40	✓
TAIL LAMP L/R X2	N/S one 0/5/11	651.20	\$1,658.80	IPC
TAIL LAMP GASKET L/R X2	11		\$256.60	X
REAR BUMPER	00/10e	1016.20	\$1,411.30	✓
REAR BUMPER SIDE RETAINER L/R X2	N/S Bent	48.50	\$168.80	IPC
REAR BUMPER BRACKET L/R X2	11		\$122.60	X
REAR BUMPER SIDE REFLECTOR L/R X2	11		\$162.40	X
REAR BUMPER REINFORCEMENT	11		\$356.10	X
END PANEL	00/10e	491.10	\$885.70	✓
END PANEL GARNISH	11	181.20	\$245.60	✓
FLOOR PANEL TOP BOARD	11		\$585.30	X
FLOOR PANEL TOOL TRAY	twi/one	401.20	\$431.80	✓
FLOOR PANEL	R		\$989.10	X
REAR FENDER LH	11		\$1,532.20	X
REAR FENDER AIR VENT LH	11		\$86.50	X
REAR FENDER INNER TRIMBOARD LH	11		\$621.30	X
REAR FENDER GLASS LH C/W MOULDING	11		\$489.70	X
REAR EXHAUST MUFFLER	R		\$1,321.60	X
REAR EXHAUST MUFFLER RUBBER HANGER X2	11		\$78.60	X
			\$19,341.00	
		Less 20%	\$3,868.20	
			\$15,472.80	

16ef	REAR BUMPER CLIPS	neu	\$60.00	30 S/N
	REAR BUMPER REVERSE SENSOR	no function	\$280.00	200 S/N
	REVERSE CAMERA	11	\$380.00	X
	TAILGATE OUTER GARNISH CLIPS	11	\$20.00	X
	TAILGATE WINDSCREEN SEALANT	neu	\$120.00	40 S/N

TAILGATE WINDSCREEN SPONGE	neu	\$80.00	20 s/w
END PANEL GARNISH CLIPS	11	\$60.00	x
END PANEL SEALANT	neu	\$100.00	50 s/w
FLOOR PANEL SEALANT	11	\$100.00	x
REAR FENDER INNER TRIMBOARD LH CLIPS	11	\$80.00	x
REAR FENDER GLASS LH SEALANT	11	\$60.00	x
REAR FENDER GLASS LH SPONGE	11	\$50.00	x
REAR NUMBER PLATE WITH CASING	scn	\$70.00	40 s/w
		<u>\$1,460.00</u>	

TO REPLACE REAR REVERSE SENSOR		\$120.00	30
TO REPLACE REAR REVERSE CAMERA	11	\$100.00	x
TO CHECK REAR WIRING		\$50.00	20
TO REMOVE AND REFIT REAR WINDSCREEN		\$150.00	120
TO REMOVE AND REPLACE REAR FENDER LEFT QUARTER GLASS	11	\$120.00	x
TO REMOVE AND REPLACE TAILGATE FITTINGS		\$120.00	50
TO REMOVE AND REPLACE REAR INTERIOR TRIMS & GARNISH		\$200.00	60
TO PROVIDE LABOUR, WORKMANSHIP		\$1,800.00	600
TO SPRAY PAINT ON AFFECTED PANELS		\$1,400.00	900
TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	11	\$160.00	x
RUST PROOFING		\$200.00	50
		<u>\$4,420.00</u>	

Total

\$21,352.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

25835.1
202
46808
380
1830
6878.08
202
5302