SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNH8664Z/2410154

18th October 2024

The Manager
Motor Claim Department
MS First Capital Insurance Ltd
16 Raffles Quay
#42-01 Hong Leong Building
Singapore 048581

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- o To display damaged parits, liming resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Projudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

Date of Accident

17th October 2024

Location

Marymount Road

Third Party Claim Vehicle No

SH 9877 K

Repair Cost For Vehicle No

SNH 8664 Z LEXUS RC F

2/5 # 2300 | 3 drys. 2ke she. Athry.

Estimate Supply of Parts & Labours

No.	Particulars	Oty	Price	Amounts	. ,
1	Front bumper side retainer L&RH	17,2	210.00	\$ 420.00	K _
2	Front fender RH	But/negod 1	2,070.30	\$ 2,070.30	_
3	Front fender cowling RH	17 1	544.20	\$ 544.20	
4	Front fender cowling clips	1 1 lset	55.00	\$ 55.00	
5	Side skirt clips	1 1 1set	2,150.00	\$ 2,150.00	
6	Front rim RH	n^{-1}	14,374.30	\$14,374.30	9
		/ 1.0	21	\$19,613.80	
		(10	6		
Labour Charges :-			Amounts		
Remove and refit, replacem re-align, knocking front bumper, headlamp RH, front fender RH, side skirt RH				\$ 4,800.00	400
Tuff-kote on damage parts ✓ 1		\$ 40.00	X		
Spray painting on damage parts		\$ 1,800.00	600		
Check all lighting after repairs		\$ 50.00	20		
Labou	r Charge			\$ 6,690.00	
Total Amount		\$26,303.80			
					2883

GST will be reflected in the final bills.

Notes: -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.