

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100341/TNP3E2
Date: 19/11/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SND7272Z	Insured Vehicle No :	SDL2525D
Date of Loss:	17/10/2024	Nature of Claim:	TP
		Claim No:	DMPC2401410H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND7272Z	Engine No:	R16B25520878
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	MRHFC5650LT000648
Reg. Date:	23/09/2021 (Man. Year: 2021)	Odometer:	33255 km
Colour:	Red		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,218.27	1,682.05	536.22	24.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,420.00	6,500.00	4,920.00	43.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,638.27	8,182.05	5,456.22	40.01
+ GST 9.00/9.00% (S\$)	1,227.44	736.38	491.06	40.01
Nett Amount (S\$)	14,865.71	8,918.43	5,947.28	40.01

INSPECTION

Date of Assignment:	18/10/2024	
Date Inspected:	30/10/2024	Inspected At: Kah Motor Co Sdn Bhd (alexandra) (HQ) 255 Alexandra Road Singapore 159937
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2024)
Parts:	143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND7272Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	110.00 FS	*30.00 FS
2	1		*PANELR.SIDE SILL	Not Necessary	456.22 FS	*- FS
3	1		*PANEL COMPR.FR.DOOR	Bent	711.90 FS	*711.90 FS
4	1		*PANELR.RR.DOOR	Bent	651.22 FS	*651.22 FS
5	1		*GARNISH ASSY,R.SIDE SILL	Cut	106.87 FS	*106.87 FS
6	1		*MOLDING ASSYR.FR.DOOR	Necessary	21.82 FS	*21.82 FS
7	1		*GARNISH ASSYR.FR.DOOR SASH	Necessary	12.37 FS	*12.37 FS
8	1		*GARNISHR.RR.DOOR QUARTER OUT	Necessary	17.62 FS	*17.62 FS
9	1		*MOLDING ASSYR.RR.DOOR	Necessary	22.87 FS	*22.87 FS
10	1		*GARNISH ASSYR.RR.DOOR SASH	Necessary	21.22 FS	*21.22 FS
11	1		*SEALR.FR.DOOR LOWER	Necessary	7.42 FS	*7.42 FS
12	1		*MOLDING ASSYR.FR.DOOR SASH	Necessary	24.07 FS	*24.07 FS
13	1		*GARNISHR.FR.CENTER CORNER	Necessary	1.42 FS	*1.42 FS
14	1		*MOLDING ASSY,R.RR.DRINNER	Necessary	46.50 FS	*46.50 FS
15	1		*GARNISHR.RR.CENTER CORNER	Necessary	1.20 FS	*1.20 FS
16	1		*SEALRR.DOOR LOWER	Necessary	5.55 FS	*5.55 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,218.27	1,682.05
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (8P)	New	3,000.00	2,080.00
2	CUT OFF & RENEW CTR PILLAR OUTER PANEL. STRAIGHTEN	New	4,000.00	1,950.00
3	REMOVE & TRANSFER ITEMS TO NEW FR R DR ADJUST	New	650.00	650.00
4	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	New	650.00	650.00
5	BODY UNDERSIDE COATING (N)	New	520.00	520.00
6	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN	New	650.00	0.00
7	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	650.00	0.00
8	RESET VEHICLE SMART ENTRY SYSTEM	New	650.00	650.00
9	REMOVE & RENEW FR SEAT FRAME INCLUDING FITTING ON	New	650.00	0.00
Gross Labour Cost (S\$)			11,420.00	6,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >