

ASS. REC. BY: Taufikh

REF: CB/ICS24100341/Tnp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$105K

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seer: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Sin Hai Vehicle: IN / OUT

Veh No: SND7272Z Yr Regn: 2021, 09

Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic 1.6 c.c. 1597

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 33255 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHEC5650LT 000648

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/55R16

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 3-10-29

Survey held at Kah Mui Mexandre

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh confirmed part by parts \$8182.05 and 6 days.
	(red, \$5456.22, 40%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 6

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS \$ _____

Photos _____

Others _____

Rep. Format: _____

Lump Sum / L.B.I. (\$ _____)

TOTAL



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ECICS LIMITED
10 EUNOS ROAD 8 #09-04A
SINGAPORE POST CENTRE
SINGAPORE 408600
Registration No : SND7272Z
Chassis No : MRHFC5650LT000648
Model : CIVIC 1.6 VTI YM2020
Owner's Name : NANCY KARTIKASARI SUTANTO
Ins Policy No. :
Date of Accident : 17/10/2024

Document No. : SQT24002827
Date : 18. Oct 2024
Customer No. : WZE001
Svc Advisor :
Engine No : R16B25520878
Date | Time : 18. Oct 2024 2:19:19 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
BOSUN	SUNDRIES	1	110.00	30	110.00	9.90	119.90
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (8P)	1	3000.00	2080	3000.00	270.00	3270.00
BKCP11R	CUT OFF & RENEW CTR PILLAR OUTER PANEL. STRAIGHTEN	1	4000.00	1950	4000.00	360.00	4360.00
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR R DR ADJUST	1	650.00	✓	650.00	58.50	708.50
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	650.00	✓	650.00	58.50	708.50
BOBC	BODY UNDERSIDE COATING (N)	1	520.00	✓	520.00	46.80	566.80
BMS02R	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN	1	650.00	X	650.00	58.50	708.50
BMS04R	REMOVE & RENEW FR SEAT FRAME INCLUDING FITTING ON	1	650.00	X	650.00	58.50	708.50
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00	X	650.00	58.50	708.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	✓	650.00	58.50	708.50
Sum Labor					11530.00	1,037.70	12,567.70
04631-TEA-T00ZZ	PANELR.SIDE SILL	1	608.30	25	456.22	41.06	497.28
67010-TEA-T00ZZ	PANEL COMPR.FR.DOOR	1	949.20	25	711.90	64.07	775.97
67510-TEA-T00ZZ	PANELR.RR.DOOR	1	868.30	25	651.22	58.61	709.83

Printed on 18/10/2024 2:29:09 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ECICS LIMITED
10 EUNOS ROAD 8 #09-04A
SINGAPORE POST CENTRE
SINGAPORE 408600
Registration No : SND7272Z
Chassis No : MRHFC5650LT000648
Model : CIVIC 1.6 VTI YM2020
Owner's Name : NANCY KARTIKASARI SUTANTO
Ins Policy No :
Date of Accident : 17/10/2024

Document No. : SQT24002827
Date : 18. Oct 2024
Customer No. : WZE001
Svc Advisor :
Engine No : R16B25520878
Date | Time : 18. Oct 2024 2:19:19 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
71800-TEA-T51ZA	GARNISH ASSY,R.SIDE SILL	1 <i>ent</i>	142.50	25	106.87	9.62	116.49
72410-TEA-T01	MOLDING ASSYR.FR.DOOR	1 <i>nei</i>	29.10	25	21.82	1.96	23.78
72430-TEA-T01	GARNISH ASSYR.FR.DOOR SASH	1 <i>nei</i>	16.50	25	12.37	1.11	13.48
72721-TEA-T01	GARNISHR.RR.DOOR QUARTER OUT	1 <i>nei</i>	23.50	25	17.62	1.59	19.21
72910-TEA-T01	MOLDING ASSYR.RR.DOOR	1 <i>nei</i>	30.50	25	22.87	2.06	24.93
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH	1 <i>nei</i>	28.30	25	21.22	1.91	23.13
Sum Item					2022.11	181.99	2,204.10

Survey By

Date & Time

Excess

Status

Signature

Tanplin 97495749
18/10/2024 12pm
06 days
p/p Resurvey before paint
tanplin@lkhauto.com

Total Amount 13,552.11 1,219.69 14,771.80

Total (Inclusive of GST) 14,771.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 18/10/2024 2:29:09 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.