


PHOTOGRAPHS FOR VEHICLE NO. : SMF 4715J



PHOTOGRAPHS FOR VEHICLE NO. : SMF 4715J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 3 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SMF 4715J

