



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100345/Rvp3m4
16 RAFFLES QUAY	Date:	26/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7899C	Veh. Inspected	SNR 6280H
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009219MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	21/10/2024

2. Vehicle Details

Make & Model	VOLKSWAGEN ID.4 PRO	C.C	-
Engine No.	-	Year of Reg.	27/06/2024
Chassis No.	WVGZZZE23RE022291	Colour	RED
Odometer	6236 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/50R19	HANKOOK	6
L/H Front Tyre	255/50R19	HANKOOK	6
R/H Rear Tyre	255/50R19	HANKOOK	6
L/H Rear Tyre	255/50R19	HANKOOK	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/10/2024	Inspection Date	23/10/2024
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.
B)DAMAGES CONSISTENT TO ACCIDENT REPORT.
C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days