

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MS First Capital Insurance Ltd

36 Robinson Road
 #16-01 City House
 Singapore 068877
 Tel : 6507 - 3848
 Fax : 6507 - 3849

Quotation

DATE : 21.10.2024
 VEH NO : SMP4618D
 MODEL : Honda Vezel
 D O A : 16.10.2024
 YR REF : SHA2848H

Yan.

Attn : Motor Claim Dept (pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMP4618D (HONDA VEZEL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Door - RH <i>Dented</i>	1	989.40 ✓
2	Front Door Lock - RH <i>new</i>	1	285.40 +
3	Front Door Weatherstripe - RH <i>new</i>	1	145.20 +
4	Front Door Inner Trim Board - RH <i>new</i>	1	645.10 +
5	Front Door Glass Regulator C/W Motor - RH <i>new</i>	1	394.60 +
6	Rocker Panel Outer Skirt <i>Regis</i>	1	678.20 +
7	Rear Door - RH <i>Dented</i>	1	980.60 ✓
8	Rear Door Lock - RH <i>new</i>	1	274.50 +
9	Rear Door Weatherstripe - RH <i>new</i>	1	148.10 +
10	Rear Door Vertical Weatherstripe - RH <i>at</i>	1	99.40 ✓
11	Rear Door Inner Trim Board - RH <i>2 new</i>	1	635.90 +
12	Rear Door Glass Regulator C/W Motor - RH <i>new</i>	1	385.50 +
13	Rear Fender Arc Garnish - RH <i>at</i>	1	196.40 ✓
14	Rear Axle <i>2 new</i>	1	1,513.20 +
15	Rear Wheel Hub C/W Bearing - RH <i>new</i>	1	335.40 +
16	Rear Shock Absorber - RH <i>new</i>	1	330.70 +
			\$ 8,037.60
Less 20%			(1,607.52)
			\$ 6,430.08

S/NETT ITEMS

1	Front Door Inner Trim Board Clips <i>new</i>	1 set	30.00 +
2	Front Door Black Tape <i>new</i>	1 set	60.00 ✓
3	Rocker Panel Outer Skirt Clips <i>new</i>	1 set	30.00 +
4	Rear Door Inner Trim Board Clips <i>new</i>	1 set	30.00 +
5	Rear Door Black Tape <i>new</i>	1 set	60.00 ✓
6	Rear Fender ARC Garnish Clips <i>new</i>	1 set	20.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SMP4618D (HONDA VEZEL)

7	Rear Wheel Rim <i>ut</i>	1	880.00 <i>480</i>
8	Rear Tyre <i>xbe new</i>	1	280.00 <i>X</i>
			\$ 1,390.00
Total parts			\$ 7,820.08

LABOUR CHARGE

1	To knocking & pull out RH front portion & renew above parts	\$ 800.00 <i>300</i>
2	To putty and spray up paint works	\$ 800.00 <i>600</i>
3	To check wiring system	\$ 50.00 <i>30</i>
4	To apply tuff coat	\$ 150.00 <i>30</i>
5	To transfer front & rear door fittings	\$ 300.00 <i>160</i>
6	To remove rear undercarriage	\$ 380.00 <i>X</i>
7	To perform wheel alignment	\$ 150.00 <i>80</i>
Total Labour		\$ 2,630.00
GRAND TOTAL		\$ 10,450.08

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 3832.64
h/s: 3050
05 Days