

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24100347/EQP3M4**Date:** 30/10/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAB00607		
Claimant Vehicle No :	SHD3856L	Insured Vehicle No :	SNN6549E		
Date of Loss:	19/10/2024	Nature of Claim:	TP	Claim No:	M2406120

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3856L	Engine No:	G4LEJU131993
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU121806
Reg. Date:	11/12/2018 (Man. Year: 2018)	Odometer:	773629 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,235.36	595.68	3,639.68	85.94
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,480.00	970.00	510.00	34.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,727.36	1,577.68	4,149.68	72.45
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	5,727.36	1,250.00	4,477.36	78.17
+ GST 9.00/9.00% (S\$)	515.46	112.50	402.96	78.17
Nett Amount (S\$)	6,242.82	1,362.50	4,880.32	78.17

INSPECTION

Date of Assignment:	21/10/2024 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969
Date Inspected:	21/10/2024 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2024)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3856L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER COVER	Broken	481.10 FL	*481.10 FL
2	1		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER SIDE BRACKER RH	Broken	28.00 FL	*28.00 FL
4	1		*FRT BUMPER MOULDING CENTRE UPPER	Not Necessary	368.50 FL	*- FL
5	1		*HEADLAMP RH	Not Necessary	2,110.30 FL	*- FL
6	1		*FRT BUMPER SIDE MOULDING RH	Broken	186.90 FL	*186.90 FL
7	1		*DAYLIGHT RH	Not Necessary	642.50 FL	*- FL
8	1		*HEADLAMP SUPPORT PANEL	Not Necessary	907.30 FL	*- FL
9	1		*FRT WHEEL HUB CAP RH	Not Necessary	346.40 FL	*- FL
10	1		*FRT FENDER SHIELD RH	Not Necessary	174.60 FL	*- FL
11	1		*EMBLEM- BLUE DRIVE RH	Necessary	26.60 FL	*26.60 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	5,294.20 744.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,058.84 148.92
					Total Parts (S\$)	4,235.36 595.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	380.00
2	SPRAY PAINTING CHARGE	New	600.00	560.00
3	CHECK ALL LIGHTING	New	80.00	30.00
Gross Labour Cost (\$\$)			1,480.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >